S89°-15'-54"E
N. LINE SE 1/4 SEC. 11
1841.68'
757.75'
25.01'
NW CORNER SE 1/4 SEC. 11
NE CORNER SE 1/4 SEC. 11
255'
0.66'
2.80'
1132'
10.747 AC. C.
11 AC. D.
S 89°-18'-00"E
706.48'
29.14'
255' D.
253.86' M.
N 0°-37'-43"E, 336.00'
82.14'
N 0°-37'-43"E
FRANKLIN E. & SHIRLEY F. RICHMOND
O.R. V-23 P-783
029-23-010-09-004
12.870 AC.
769.00'
N
0 100'
SCALE
M-MEASURED
C-CALCULATED
D-DEED
DATE 8-16-89
REV. 9-6-89
REV. 2-1-90
N 7°-42'-45"E
277.00'
CAROLE L. & PAUL E. MILLER
V-835 P-9
16.787 AC. C.
16.6 AC. D.
CHARLES A. & CELESTE J.W. MARBY
O.R. V-24 P-5
029-23-010-09-005
13.766 AC.
R=1637.02'
A=735.72'
C=434.44'
S 6°-59'-49"E
R=1637.02'
A=379.15'
C=378.30'
N 6°-00'-25"W
Dc=3°-30'
974'
N 52°-40'-33"E, 727'
639.61'
30.41'
191.50'
N89°-36'-31"W
N1°-22'-23"E
61.50'
516.5' D.
513.35' M.
N 89°-36'-31"W
31.0'
1.5'
R=1637.02'
A=56.57'
C=56.57'
N 13°-37'-55"W
DUE EAST
1340.86'
25.84'
145.04'
87.39'
579' D.M.
570.31' M.
N 64°-34'-20"E
1249.67'
DUE EAST
60'
162.01'
25.84'
029-23-010-09-006
10.000 AC.
348.08'
336.81'
FRANKLIN E. & SHIRLEY F. RICHMOND
O.R. V-23 P-781
029-23-010-10-000
14.744 AC.
-5.000 AC.
9.744 AC.
2.5'
1337.00'
DUE EAST
25.84'
T.R. LEXINGTON-FREDERICKTOWN RD. (50')
N 34°-54' E, 546.5'
W. LINE SE 1/4 SEC. 11
N 0°-05'-30"W
149.24'
E. LINE SE 1/4 SEC. 11
N 1°-22'-23"E
701.53'
25.86'
S89°-46'-31"E
487.68'
601.78'
N 14°-37'-19"W
421.91'
5.000 AC.
438.80'
JERALD L. & CYNTHIA L. LAYFIELD
O.R. V-22 P-475
029-23-010-09-003
27.327 AC.
N 0°-05'-30"W, 1694.65'
697.84'
EMORY L. MYERS
V-231 P-549
22.485 AC.
26.42'
N 88°-30'-25"W
268.67'
1.00 AC.
WARREN DAVID & VANESSA LYNN RUHL
V-860 PG. 563
S 1°-33'-43"W
150.00'
158.58'
214.44'
1.22'
355' D.M.
351.72' M.
S 60°-39'-50"W
24.88'
1219.43'
N 88°-42'-37"W
316.13'
S 88°-29'-46"E
26.42'
ROBERT D. JR. & MARTHA L. FORSYTHE
V-681 P-253
2.990 AC. C.
3.1 AC. D.
640' D.
638.78' C.
431.40' C.
484.4' D.
490.5'
660'
DR. ROBERT DOUGLAS & CATHERINE C. MYERS
V-723 P-640
21.074 AC. C.
20.5 AC. D.
S 88°-37'-49"E
621.57' C.
610' D.
N 0°-05'-30"W
250'
3.791 AC. C.
4 AC. D.
N 17°-22'-23"W
263.92' C.
167' D.
146.56' C.
S 88°-37'-49"E
147.8'
148.46' C.
T.H. 128
156.99'
96.11' C.
SW CORNER SE 1/4 SEC. 11
692.00'
1140' D.
1042.93' M.
N 88°-37'-49"W
S. LINE SE 1/4 SEC. 11
700'

PRINTED
FEB 2 1990
SHAFFER, JOHNSTON, LICHTENWALTER & ASSOC.

△ CORNER FENCE POST FOUND
□ RAILROAD SPIKE FOUND
○ IRON PIN FOUND
■ RAILROAD SPIKE SET
◎ IRON PIN SET - 5/8" DIA. REINFORCING ROD WITH PLASTIC CAP STAMPED "S.J.L. INC."

BEARINGS ARE TO AN ASSUMED MERIDIAN AND ARE USED TO EXPRESS ANGLES ONLY.

BEING PART OF THE SE 1/4 OF SEC. 11, T-19, R-19, PERRY TWP., RICHLAND CO., OHIO

STATE OF OHIO
ROGER L. STEVENS
7052
REGISTERED SURVEYOR

Roger L. Stevens
ROGER L. STEVENS
REG. SURVEYOR #7052
SM 1653

SURVEY FOR JACK MYERS

SHAFFER, JOHNSTON, LICHTENWALTER & ASSOCIATES, INC.
CONSULTING ENGINEERS - SURVEYORS
MANSFIELD OHIO WOOSTER