


CURVE "A"
 R=5727.40'
 $\Delta=02^{\circ}01'51''$
 L=203.00'
 BRG=S 33°33'31" E
 C LEN=202.99'

CURVE "B"
 R=5697.40'
 $\Delta=02^{\circ}43'04''$
 L=270.26'
 BRG=S 31°10'24" E
 C LEN=270.23'

CURVE "C"
 R=5727.40'
 $\Delta=02^{\circ}43'13''$
 L=271.93'
 BRG=N 31°11'00" W
 C LEN=271.91'

- LEGEND
- ▲ RR SPIKE FOUND
 - IRON PIN FOUND
 - ⊕ MAG NAIL SPIKE SET
 - ⊗ IRON PIN SET WITH CAP STAMPED "SEILER 6869"



BEARINGS ARE BASED ON AN ASSUMED MERIDIAN

RICHLAND TRUST CO., TRUST
 O.R.V. 694, PAGE 57

R. E. YETZER
 DEED VOLUME 874, PAGE 291

M. & J. YETZER
 O.R.V. 360, PAGE 968

S. METZ
 O.R.V. 368, PAGE 494

THE PLACE OF BEGINNING
 PARCEL "A"

THE PLACE OF BEGINNING
 PARCEL "B"

LIGHTHOUSE CHAPEL INC.
 O.R.V. 571, PAGE 851


F. HERR
 O.R.V. 250, PAGE 284

R. & B. BLANTON
 O.R.V. 746, PAGE 873

J. CHATLAIN
 E. CHATLAIN
 O.R.V. 366, PAGE 384

PARCEL "A" 4.81 ACRES

PARCEL "B" 0.19 ACRES



NEW SURVEY
 OF EXISTING PARCEL
 RICHLAND COUNTY
 TAX MAP OFFICE
 INITIAL DATE
 JCS 2-1-01

NEW SPLIT
 RICHLAND COUNTY
 TAX MAP OFFICE
 INITIAL DATE
 JCS 2-1-01

SURVEY PLAT FOR
LIGHTHOUSE CHAPEL INC.
 PART SW QTR. SEC. 25, T-21, R-18
 MADISON TOWNSHIP
 RICHLAND COUNTY, OHIO
 DATE: JANUARY 25, 2001 SCALE: 1"=50'
 CHAT2.DWG

Douglas C. Seiler
 DOUGLAS C. SEILER
 PROFESSIONAL SURVEYOR #6869
 52 1/2 NORTH MAIN STREET
 MANSFIELD, OHIO 44902
 PHONE (419) 525-3644
 FAX (419) 525-3696

2/01/01
 DATE