NEW SURVEY OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE EAK 6-26-23 INITIAL & DATE PP-157 8 60. ARLINGTON AVENUE-(60') P.O.B. 253.04' N 89°34'57" E 88.00' D.&C. PART LOT #3171 ≥ PART LOT #317 01°11′36″ 65.78′-0. 0.1079 AC. 4698.84 Sq. Ft. CHARLES A. G VICTORIA L. DV. 808, 107 BIGELOW ENTERPRISES, LLC ORV. 2731, PG. 671 54.87'-0. 89°34'57" 117.50 PART LOT #3172 NOTE: PARCEL SUBJECT TO AND BENEFITING BY JOINT GARAGE AND DRIVEWAY EASEMENT (SEE DV. 182, PG. 183 AND DV. 808, PG. 697) COLEMAN ROAD-(52') WWW. <u>LEGEND</u> C. - CALCULATED DISTANCE D. - DEED DISTANCE O. - OBSERVED DISTANCE В. P. - PLATTED DISTANCE AMSE O IRON PIN/PIPE FOUND 8396 X DRILL HOLE SET WITH CROSS CUT IN CONCRETE 60' 0' 15' IRON PIN SET-5/8" REBAR SET WITH I.D. CAP STAMPED "RAMSEY S-8396" SCALE: 1" 30 RAMSEY SURVEYING Distances shown hereon are expressed in feet and decimal parts Professional Land Surveying Services 283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com Bearings are to an assumed meridian and are used to express angles only. SURVEY MADE FOR PROPERTY TRANSFER CERTIFICATION: I hereby state that the foregoing survey was prepared from actual field measurements, In accordance with BEING A PART OF LOT #3171, ARLINGTON ADDITION, PLAT BOOK 4, PAGE 48, CITY OF MANSFIELD, Chapter 4733—37, Ohio Administrative Code. RICHLAND COUNTY, OHIO 06/16/2023 $1^{SCALE} = 30^{\circ}$ 06/19/202.

JOB NO: SM-5843 SHEET 1 OF Nathaniel B. Ramsey, P.S Date 06/19/2023

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

June 19, 2023

Situated in the City of Mansfield, County of Richland, State of Ohio and being a part of Lot 3171 of Arlington Addition as recorded in Plat Book 4, page 48, being a parcel conveyed to Bigelow Enterprises, LLC. by official record volume 2731, page 671 and being more particularly described as follows:

Beginning for the same at an iron pin set in the northeast corner of said Lot 3171, being at the intersection of the south existing right of way line of Arlington Avenue-(60' R/W) with the westerly existing right of way line of Marion Avenue-(60' R/W);

Thence, the following FOUR courses:

- 1. **South 25 degrees 41 minutes 30 seconds West, 73.25 feet** along said westerly line of Marion Avenue to an iron pin set in the southeast corner of said Lot 3171;
- 2. **South 89 degrees 34 minutes 57 seconds West, 54.87 feet** along the south line of said lot to an iron pin set in the southeast corner of a parcel conveyed to Charles A. Glorioso and Victoria L. Glorioso by deed volume 808, page 694;
- 3. North 01 degree 11 minutes 36 seconds West, 65.78 feet along the east line of said Glorioso parcel to a drill hole with cross-cut set in the northeast corner thereof, said drill hole also being on the north line of aforementioned Lot 3171, the south line of Arlington Avenue;
- 4. **North 89 degrees 34 minutes 57 seconds East, 88.00 feet** along the north line of said lot, the south line of Arlington Avenue to the **Place of Beginning**, containing a total of 0.1079 of an acre (4698.84 square feet), more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

According to a survey made in June 2023 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-5805_Legal

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

EAK 6-26-23

INITIAL & DATE

PP-157