
SITUATED IN MONROE TOWNSHIP, RICHLAND COUNTY, STATE OF OHIO



Situated in Monroe Township, Richland County, State of Ohio and being a part of the Northwest Quarter of Section 8, Township 22, Range 17 and being more fully described as follows:

Beginning at an iron pin at the Northwest Corner of Section 8; thence South 89° 45' 00" East along the North Line of said Section, a distance of 201.30 feet to an iron pin; thence South 19° 15' 30" East a distance of 580.52 feet to an iron pin; thence South 29° 55' 00" East, a distance of 1105.67 feet to an iron pin; thence South 37° 05' 00" West, a distance of 150.37 feet to a spike set in the Centerline of State Route 39; thence North 51° 37' 30" West along the Centerline of said highway, a distance of 60.00 feet to a spike, the true place of beginning; thence continuing North 51° 37' 30" West, a distance of 204.00 feet to a spike set in the Centerline of State Route 39; thence North 38° 25' 30" East and passing through an iron pin set 30.00 feet from the Centerline of said highway, a distance of 132.00 feet to an iron pin; thence South 35° 24' 30" East, a distance of 212.28 feet to an iron pin; thence South 38° 19' 30" West, and passing through an iron pin set 30.00 feet from the Centerline of State Route 39, a distance of 72.70 feet to a spike, the true place of beginning, containing 20,622 sq. feet of land which is .4734 Acres of land and subject to all legal highways.

Robert O. Schneider Jr.

Registered Surveyor No. 5054