


I HEREBY CERTIFY THE WITHIN PLAT
AND MEASUREMENTS TO BE CORRECT.

Wm. L. Borchardt

Surveyor



TROY TWP.
PT. N.E. 1/4 + N.W. 1/4 SEC. 2 TWP. 20 R. 19