SURVEY FOR: CLEARVIEW REALTY PART OF THE SE. 1/4 OF SEC. 23, T-20, R-20, SANDUSKY TWP., RICHLAND CO., STATE OF OHIO. LOCATION: DATE: 5-11-22 JOB NUMBER: SANDUSKY-23 KELLER REAL ESTATE LTD. O.R.V.-2200 P.-435 р N 88°33'49" E р 150.22 a 23 A SEC. 4 SE. KELLER REAL ESTATE LTD. O.R.V.-2655 P.-186 Щ JUSTIN E. BOOR 0.R.V.-1884 P.-535 605.6 WELLS FARGO USA HOLDINGS INC. al. 0.R.V.-2990 P.-4699 00.31 1.996 Acres JUSTIN BOOR O.R.V.-2309 P.-620 Q_S.R. 309 (60') KELLER REAL ESTATE LTD. O.R.V.-2200 P.-435 100 200' S. LINE SE. 1/4 SEC. 23 SCALE 1"=100' **LEGEND** 0 IRON PIN FOUND IRON PIN SET, 5/8" DIA. ROD WITH PLASTIC CAP STAMPED "STEVENS 7052" **NEW SURVEY** OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE <u>5-18-22</u> ROGER L. EAK INITIAL DATE **STEVENS** 00-162 7052 EGISTERED L. Stevens, P.S. #7052 Distances shown hereon are expressed in feet and decimal parts thereof, bearings are to an assumed meridian and are used to express angles only. CERTIFICATION: I hereby certify that the foregoing survey was prepared from actual field measurements, In accordance with Chapter 4733—37, Ohio Administrative Code and is correct to the best of my knowledge.

SURVEYOR'S DESCRIPTION FOR CLEARVIEW REALTY

1.996 Acres

Situated in the Township of Sandusky, County of Richland, State of Ohio, being part of the Southeast Quarter of Section 23, Township 20, Range 20 and being more particularly described as follows:

Beginning at a point being the intersection of the east line of said Southeast Quarter and the centerline of S.R. 309(60'), said point being referenced by an iron pin set N 00° 33' 56" E, 32.58 feet from said point;

Thence with the following FOUR courses:

- 1) **S 69° 50' 39" W, 160.06 feet** along said centerline of S.R. 309(60') to a point being the southeasterly corner of a parcel of land conveyed to Justin E. Boor by official records volume 1884, page 535, said point being referenced by an iron pin found N 00° 31' 32" E, 31.44 feet from said point;
- 2) N 00° 31' 32" E, 605.63 feet along the east line of said land of Justin E. Boor to an iron pin set in the northeast corner of said land, said iron pin also being in a southerly line of a parcel of land conveyed to Keller Real Estate Ltd. by official records volume 2200, page 435 and passing through previously referenced iron pin found at 31.44 feet;
- 3) N 88° 33' 49" E, 150.22 feet along said southerly line of said land of Keller Real Estate Ltd. to an iron pin found in a southeast corner of said land, said iron pin also being in said east line of said Southeast Quarter;
- 4) S 00° 33' 56" W, 554.25 feet along said east line of said Southeast Quarter to the place of beginning, passing through previously referenced iron pin set at 521.67 feet and containing 1.996 acres, more or less, and subject to all legal highways and easements of record.

Bearings are to an assumed meridian and are used to express angles only.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in May 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

Roger L. Stevens

Registered Surveyor No. 7052

SANDUSKY-23

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

AK 5-18-22

INITIAL DATE

00-162