

## SURVEYOR'S DESCRIPTION FOR ROBERT NELSON

## 12.539 Acres

Situated in the Township of Franklin, County of Richland, State of Ohio and being part of the Southwest Quarter of Section 7, Township 22, Range 18 and being more particularly described as follows:

**Commencing** at a railroad spike found in the intersection of the centerline of Roush Road (T.H. 197)(40') and the centerline of Richland Run Road (T.H. 239)(40'), said railroad spike also being in west line of said Southwest Quarter;

Thence S 88° 41' 47" E, 148.69 feet along said centerline of Roush Road (T.H. 197)(40') to a railroad spike found, said railroad spike being the **true place of beginning**;

Thence with the following **FIVE** courses:

- 1) **S 88° 41' 47" E, 213.67 feet** and continuing along said centerline of Roush Road (T.H. 197)940') to a railroad spike found;
- 2) **S 78° 13' 45" E, 265.59 feet** and continuing along said centerline of Roush Road (T.H. 197)(40') to a point, said point being referenced by an iron pin set S 01° 15' 50" W, 20.34 feet from said point;
- 3) S 01° 15' 50" W, 1,108.51 feet to an iron pin set in the south line of said Southwest Quarter and passing through previously referenced iron pin set at 20.34 feet;
- 4) S 89° 38' 45" W, 475.00 feet along said south line of said Southwest Quarter to an iron pin found;
- 5) N 01° 15' 50" E, 1,170.50 feet to the true place of beginning, passing through an iron pin found at 1,150.50 feet and containing 12.539 acres, more or less, and subject to all legal highways and easements of record.

Basis of bearings: Survey F-4-227.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in June 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

Roger L. Stevens Registered Surveyor No. 7052 FRANKLIN 7

NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE

EAK 6-28-22

INITIAL DATE

00-214

## **9.783** Acres

Situated in the Township of Franklin, County of Richland, State of Ohio and being part of the Southwest Quarter of Section 7, Township 22, Range 18 and being more particularly described as follows:

**Commencing** at a railroad spike found in the intersection of the centerline of Roush Road (T.H. 197)(40') and the centerline of Richland Run Road (T.H. 239)(40'), said railroad spike also being in west line of said Southwest Quarter;

Thence S 88° 41' 47" E, 362.36 feet along said centerline of Roush Road (T.H. 197)(40') to a railroad spike found;

Thence S 78° 13' 45" E, 265.59 feet and continuing along said centerline of Roush Road (T.H. 197)(40') to a point, said point being referenced by an iron pin set S 01° 15' 50" W, 20.34 feet from said point and being the **true place of beginning**;

Thence with the following FOUR courses:

- 1) S 78° 13' 45" E, 406.66 feet and continuing along said centerline of Roush Road (T.H. 197)(40') to a point, said point being referenced by an iron pin set S 01° 15' 50" W, 15.87 feet from said point;
- 2) **S 01° 15' 50" W, 1,023.06 feet** to an iron pin set in the south line of said Southwest Quarter and passing through previously referenced iron pin set at 15.87 feet;
- 3) S 89° 38' 45" W, 400.00 feet along said south line of said Southwest Quarter to an iron pin found;
- 4) N 01° 15' 50" E, 1,108.51 feet to the true place of beginning, passing through previously referenced iron pin set at 1,088.17 feet and containing 9.783 acres, more or less, and subject to all legal highways and easements of record.

Basis of bearings: Survey F-4-227.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in June 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

L. ★ RR R

Roger L. Stevens

Registered Surveyor No. 7052

FRANKLIN 30

NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE

EAK 6-28-22

00-214

## **7.031** Acres

Situated in the Township of Franklin, County of Richland, State of Ohio and being part of the Southwest Quarter of Section 7, Township 22, Range 18 and being more particularly described as follows:

**Commencing** at a railroad spike found in the intersection of the centerline of Roush Road (T.H. 197)(40') and the centerline of Richland Run Road (T.H. 239)(40'), said railroad spike also being in west line of said Southwest Quarter;

Thence S 88° 41' 47" E, 362.36 feet along said centerline of Roush Road (T.H. 197)(40') to a railroad spike found;

Thence S 78° 13' 45" E, 672.25 feet and continuing along said centerline of Roush Road (T.H. 197)(40') to a point, said point being referenced by an iron pin set S 01° 15' 50" W, 15.87 feet from said point and being the **true place of beginning**;

Thence with the following **FOUR** courses:

- 1) **S 78° 13' 45" E, 307.07 feet** and continuing along said centerline of Roush Road (T.H. 197)(40') to a railroad spike found in the west line of a parcel of land conveyed to The Samuel G. Roush Trust etc. by official records volume 395, page 340;
- 2) S 00° 22' 31" W, 958.23 feet along said west line of said land of The Samuel G. Roush Trust etc. to an iron pin found in the southwest corner of said land, said iron pin also being in the south line of said Southwest Quarter and passing through an iron pin found at 20.00 feet;
- 3) S 89° 38' 45" W, 316.91 feet along said south line of said Southwest Quarter to an iron pin set;
- 4) N 01° 15' 50" E, 1,023.06 feet to the true place of beginning, passing through previously referenced iron pin set at 1,007.19 feet and containing 7.031 acres, more or less, and subject to all legal highways and easements of record.

Basis of bearings: Survey F-4-227.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in June 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

Roger L. Stevens

Registered Surveyor No. 7052

FRANKLIN 30

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

EAK 6-28-22
INITIAL DATE

00-214