


NORTH



BEARINGS ARE BASED ON THE RIGHT OF WAY PLANS FOR STATE ROUTE 30, ON FILE AT THE RICHLAND COUNTY TAX MAP OFFICE, AND ARE INTENDED TO BE USED USED FOR ANGULAR DETERMINATION ONLY.



**CURVE 1**  
R=4232.28'  
Δ=20°52'26"  
L=1541.89'  
BRG=S 65°53'37" W  
C LEN=1533.37'

**CURVE 2**  
R=4232.28'  
Δ=06°21'01"  
L=469.07'  
BRG=S 79°30'20" W  
C LEN=468.83'

**CURVE 3**  
R=1432.69'  
Δ=00°50'52"  
L=21.20'  
BRG=N 72°15'21" E  
C LEN=21.20'

THE EAST LINE OF THE NE QTR. SEC 24

N 01°16'07" E  
350.37'

THE NORTH LINE OF THE SE QTR. SEC. 24

THE NE CORNER OF THE SE QTR. SEC 24

US ROUTE 30

SOUTHERLY R/W LINE

CURVE 2

THE PLACE OF BEGINNING

A. P. DINGER  
O.R.V. 80, PAGE 830

J. & V. REEF  
O.R.V. 82, PAGE 135

14.41 ACRES

D. J. FOGLE  
O.R.V. 1011, PAGE 440

S 00°29'48" E 934.53'

N 38°57'51" W 875.35'

CURVE 3

N 72°40'51" E 965.51'


MANSFIELD - GALLON ROAD (STATE ROUTE 309)

LEGEND

- IRON PIN FOUND
- ▲ RR SPIKE FOUND
- ⊕ MAG NAIL SPIKE SET
- ⊗ IRON PIN SET WITH CAP STAMPED "SEILER 6869"

NEW SPLIT  
RICHLAND COUNTY  
TAX MAP OFFICE  
EAK 1-8-03  
INITIAL DATE

*Douglas C. Seiler*  
SURVEYED BY: DOUGLAS C. SEILER  
PROFESSIONAL SURVEYOR #6869  
52-1/2 NORTH MAIN STREET  
MANSFIELD, OHIO 44902  
(419) 525-3644  
FAX (419) 525-3696



APPROVED THIS 7 DAY OF Jan, 2003

*Jim Wolf*  
JIM WOLF  
SANDUSKY TOWNSHIP  
ZONING INSPECTOR

SURVEY PLAT FOR  
DINGER

PART SE QTR. SEC. 24, T-20, R-20  
SANDUSKY TOWNSHIP  
RICHLAND COUNTY, OHIO

DATE: JULY 3, 2002 SCALE: 1"=100'

DINGER2