



THIS SURVEY DOES NOT MEET OAC 4733-37 AND IS FOR FILE ONLY
 EAK dd-139 5-31-12



- LEGEND**
- IRON PIN/PIPE FOUND
 - LATH SET ON LINE
 - IRON PIN SET-5/8" REBAR SET WITH I.D. CAP STAMPED "SUL INC"

Distances shown hereon are expressed in feet and decimal parts thereof.

Basis of Bearings survey F-3-47.

CERTIFICATION: I hereby state that the foregoing survey was prepared from actual field measurements, in accordance with Chapter 4733-37, Ohio Administrative Code.

By: Roger L. Stevens 5-31-12 Date
 Roger L. Stevens, P.S. #7052
 for Shaffer, Johnston, Lichtenwalter,
 & Associates, Inc.



SHAFFER, JOHNSTON, LICHTENWALTER & ASSOCIATES, INC.
 Consulting Engineers & Surveyors
 909 South Main Street Mansfield, Ohio 44807
 TEL (419) 756-7302
 FAX (419) 756-0867 EMAIL karnstutz@sjl-inc.com

SURVEY MADE AT THE REQUEST OF:

BARBARA SIEMBIDA
 PART OF THE SOUTHEAST & NORTHEAST QUARTERS
 OF SECTION 16, MIFFLIN TOWNSHIP
 T-23 N. R-17 W
 RICHLAND COUNTY, OHIO

DRAWN RLS	CHECKED KAA	SCALE 1" = 100'	DATE 05/21/2012
DWG NO: SM-2053	JOB NO: SM-2053	SHEET 1 OF 1	