

Roger L. Stevens

August 20, 1997

SURVEYOR'S DESCRIPTION FOR
JAMES R. JARVIS

Lots 549 Through 552

Situated in the Village of Butler, County of Richland, State of Ohio and being all of lots 549 through 552 of the consecutively numbered lots in said village as shown in volume 10, page 18 of Richland County Plat records and being more particularly described as follows:

Beginning at an iron pin set in the southwest corner of said lot 549, said iron pin also being in the intersection of the north line of Roosevelt Street (50 feet) and the east line of Craig Street (50 feet);

Thence N 00° 25' 45" E, 100.00 feet along the west line of said lots 549 through 552, also being along said east line of Craig Street to an iron pin set in the northwest corner of said lot 552;

Thence S 89° 14' 46" E, 125.00 feet along the north line of said lot 552 to an iron pin set in the northeast corner of said lot;

Thence S 00° 25' 45" W, 100.00 feet along the east line of said lots 549 through 552 to an iron set in the southeast corner of said lot 549, said iron pin also being in said north line of Roosevelt Street;

Thence N 89° 14' 46" W, 125.00 feet along said north line of Roosevelt Drive also being the south line of said lot 549 to the place of beginning and containing 0.287 acre, more or less, but subject to all legal highways and easements of record.

Bearings are to an assumed meridian and are used to express angles only.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in August 1997 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

I-203

H-205

Surveyor's Description
James R. Jarvis

-2-

August 20, 1997

Lots 553 Through 556

Situated in the Village of Butler, County of Richland, State of Ohio and being all of lots 553 through 556 of the consecutively numbered lots in said village as shown in volume 10, page 18 of Richland County plat records and being more particularly described as follows:

Beginning at an iron pin set in the northeaster corner of said lot 556, said iron pin also being in the south line of Scott Avenue (50 feet);

Thence S 00° 25' 45" W, 100.00 feet along the east line of said lots 553 through 556 to an iron pin set in the southeast corner of said lot 553;

Thence N 89° 14' 46" W, 125.00 feet along the south line of said lot 553 to an iron pin set in the southwest corner of said lot, said iron pin being in the east line of Craig Street (50 feet);

Thence N 00° 25' 45" E, 25.00 feet along the east line of said lot 553 also being said east line of Craig Street to an iron set in the northwest corner of said lot, said iron pin also being in southwest corner of said lot 554;

Thence N 14° 07' 27" W, 25.87 feet along the westerly line of said lot 554 also being said east line of Craig Street to an iron pin set in the northwest corner of said lot, said iron pin also being in the southwest corner of said lot 555;


Thence N 46° 51' 38" W, 74.17 feet along the westerly line of said lots 555 and 556 also being along the easterly line of Craig Street to an iron pin set in the northwest corner of said lot 556, said iron pin being in the intersection of said easterly line of Craig Street and the south line of Scott Avenue;

Thence S 89° 14' 46" E, 186.00 feet along said south line of Scott Avenue also being the north line of said lot 556 to the place of beginning and containing 0.328 acre, more or less, but subject to all legal highways and easements of record.

Bearings are to an assumed meridian and are used to express angles only.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in August 1997 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.



NEW SURVEY
OF EXISTING PARCEL
TAX MAP APPROVED
A.B. 8-20-97
INITIAL DATE

Roger L. Stevens

Roger L. Stevens
Registered Surveyor No. 7052
SM1544CC

H-205