

Plat Survey

for

Lee Harp

Being a part of the South-West Qtr., Sect. 21, Twp. 23, R. 17, Mifflin Township, Richland County, Ohio
April 8, 1989

D. E. Coudill

V-877, P-174 - 1.392 Ac.

D. & L. Harp

V-842, P-745 - 3.608 Ac.

Strooke Ave. 60' R/W

N 88° 20' E 21'

268.0'

0.084 Ac.

305.25'

1.877 Ac.

S 2° 30' E 305.25'

S 88° 20' W - 268.0'

280.0'

305.24'

1.961 Ac.

N 2° 30' W 305.24'

S 88° 20' W 280.0'

S.W. Cor, S.W. Qtr., Sect. 21

N 88° 20' E - 1380.0'


Peterson Rd. T.H. 295

South line, S.W. Qtr., Sect. 21


Vernon F. Harp
F Sons Inc
V-580, P-259

N

1" = 100'



K-48



Larry G. Blunk
Professional Surveyor
Lic. # 6320
Rev. 6/18/89 (0.084 Ac.)

● R.R. Spike Found

○ I.P. Set-Capped "Blunk-6320"

Basis of Bearings: Deed Vol. 842, P-745