

SURVEYOR'S DESCRIPTION FOR BRENT TAYLOR

Situated in the Township of Worthington, County of Richland, State of Ohio, being part of the Southeast Quarter of Section 13, Township 21, Range 17, and being more particularly described as follows:

Beginning at a railroad spike found in the southwest corner of said Southeast Quarter, said railroad spike also being in the intersection of the centerline of S.R. 97 (60') and the centerline of McCurdy Road (C.H. 378)(60');

Thence with the following TEN courses:

- 1) N 01° 04' 11" W, 443.04 feet along said west line of said Southeast Quarter and along said centerline of McCurdy Road (C.H. 378)(60') to a point, said point being referenced by an iron pin set N 88° 13' 04" E, 29.11 feet from said point;
- 2) N 88° 13' 04" E, 797.81 feet to an iron pin set and passing through previously referenced iron pin set at 29.11 feet;
- 3) N 03° 03' 18" W, 383.00 feet to an iron pin set;
- 4) S 88° 17' 30" W, 784.53 feet to a point being in said west line of said Southeast Quarter and being in said centerline of McCurdy Road (C.H. 378)(60') and passing through an iron pin set at 757.94 feet;
- 5) N 01° 04' 11" W, 500.96 feet along said west line of said Southeast Quarter and along said centerline of McCurdy Road (C.H. 378)(60') to a point being the southwest corner of a parcel of land conveyed to R-3 Land LLC by official records volume 2445, page 90, said point being referenced by an iron pin found N 88° 56' 49" E, 25.00 feet from said point;
- 6) N 88° 56' 49" E, 1,355.62 feet along the south line of said land of R-3 Land LLC to an iron pin found in the southeast corner of said land, said iron pin also being in the west line of a parcel of land conveyed to Margaret A. Marlow by official records volume 2582, page 219 and passing through previously referenced iron pin found at 25.00 feet and passing through an iron pin found at 548.76 feet;
- 7) S 01° 00' 44" E, 526.59 feet along said west line of said land of Margaret A. Marlow to an iron pin set;
- 8) N 89° 45' 14" W, 257.19 feet to an iron pin set;
- 9) S 01° 54' 07" W, 794.56 feet to a point being in the south line of said Southeast Quarter, said point also being in said centerline of S.R. 97 (60') and passing through as iron pin set at 776.85 feet;
- 10) S 88° 12' 19" W, 1,056.85 feet along said south line of said Southeast Quarter and along said centerline of S.R. 97 (60') to the place of beginning and containing 29.048 acres, more or less, and subject to all legal highways and easements of record.;

Basis of bearings: Survey II-157.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in May 2023 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

NEW SURVEY OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE

EAK 6-7-23

INITIAL & DATE

PP-131



Roger L. Stevens

Registered Surveyor No. 7052

SM-1736A12