

LINE	BEARING	DISTANCE
L1	N 89°44'26" W	148.59
L2	N 71°27'59" E	<i>293.00'</i>
L3	N 88°58'41" E	311.98'



SURVEY BY:

CHAD F. CRAIG P.S. #8195 for SEILER & CRAIG SURVEYING INC. 270 PARK AVENUE WEST MANSFIELD, OHIO 44902 (419) 525—3644

EMAIL:SEILERANDCRAIG@SEILERANDCRAIG.COM

LEGEND

- IRON PIN FOUND
- IRON PIPE FOUND
- ⊗ 3" SURVEY MARKER SET
- △ RAILROAD SPIKE SET
- RAILROAD SPIKE FOUND
- X 5/8" IRON PIN SET WITH CAP STAMPED "CRAIG 8195"

SURVEY PLAT FOR PROPERTY TRANSFER

PART NW QTR. SEC. 24, T-19, R-19 PERRY TOWNSHIP RICHLAND COUNTY, OHIO

DATE: MAY 22, 2023 SCALE: 1"=300'

ST_RT_546_VANDYKE

SURVEY DESCRIPTION PARCEL "A"

PART OF THE NW QUARTER OF SECTION 24 PERRY TOWNSHIP RICHLAND COUNTY, OHIO

Situated in the Township of Perry, County of Richland, State of Ohio and being a part of the Northwest quarter of Section 24 of Township 19 North, Range 19 West, and being more particularly described as follows:

Beginning for the same at a point marking the southeast corner of said quarter and being a point in the centerline of Darlington East Road (C.H. 27), and being referenced by an iron pin found on a bearing of North 01 degree 18 minutes 02 seconds West and at a distance of 15.40 feet, Thence, North 89 degrees 44 minutes 26 seconds West with the south line of said quarter and with said centerline 148.59 feet to a railroad spike found marking the intersection of said centerline with the centerline of State Route 546;

Thence, North 21 degrees 58 minutes 47 seconds West with the centerline of State Route 546, 733.59 feet to a point referenced by an iron pin found on a bearing of North 89 degrees 44 minutes 26 seconds West and at a distance of 32.41 feet;

Thence, North 21 degrees 17 minutes 20 seconds West with said centerline 675.39 feet to a point referenced by an iron pin set on a bearing of North 71 degrees 27 minutes 59 seconds East and at a distance of 30.00 feet;

Thence, North 71 degrees 27 minutes 59 seconds East passing through said iron pin set, a total distance of 293.00 feet to an iron pin set;

Thence, North 21 degrees 17 minutes 20 seconds West 475.61 feet to an iron pin set on the south line of a parcel currently owned by J. & K. Mould (ORV 2428, Page 550);

North 88 degrees 58 minutes 41 seconds East with the south line of said Mould parcel and the easterly prolongation thereof 521.19 feet to an iron pin set on the east line of said quarter;

Thence, South 01 degree 18 minutes 02 seconds East with the east line of said quarter and passing through an iron pin found at a distance of 1840.91 feet, a total distance of 1856.31 feet to the place of beginning, containing 17.50 acres according to a survey by Chad F. Craig P.S. #8195 for Seiler & Craig Surveying, Inc. on May 22, 2023, but subject to all easements, right of ways and highways of record.

Iron pins set are 5/8" rods with caps stamped "CRAIG 8195".

Bearings are based on State Plane Grid North, NAD 83 (2011), Geoid 18A, Ohio North Zone and are intended to be used for angular determination only.

CHAD F. CRAIG 8195

NEW SURVEY OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE

EAK 6-15-23

INITIAL & DATE

PP-145

Chad F. Craig P.S.#8195 for Seiler & Craig Surveying, Inc.

SURVEY DESCRIPTION PARCEL "B"

PART OF THE NW QUARTER OF SECTION 24 PERRY TOWNSHIP RICHLAND COUNTY, OHIO

Situated in the Township of Perry, County of Richland, State of Ohio and being a part of the Northwest quarter of Section 24 of Township 19 North, Range 19 West, and being more particularly described as follows:

Commencing at a point marking the southeast corner of said quarter and being a point in the centerline of Darlington East Road (C.H. 27), and being referenced by an iron pin found on a bearing of North 01 degree 18 minutes 02 seconds West and at a distance of 15.40 feet, Thence, North 89 degrees 44 minutes 26 seconds West with the south line of said quarter and with said centerline 148.59 feet to a railroad spike found marking the intersection of said centerline with the centerline of State Route 546, Thence, North 21 degrees 58 minutes 47 seconds West with the centerline of State Route 546, 733.59 feet to a point referenced by an iron pin found on a bearing of North 89 degrees 44 minutes 26 seconds West and at a distance of 32.41 feet, Thence, North 21 degrees 17 minutes 20 seconds West with said centerline 675.39 feet to a point referenced by an iron pin set on a bearing of North 71 degrees 27 minutes 59 seconds East and at a distance of 30.00 feet, said point being the place of beginning of the parcel herein described;

Thence, North 21 degrees 17 minutes 20 seconds West with said centerline 569.59 feet to a point referenced by an iron pin found on a bearing of North 88 degrees 58 minutes 41 seconds East and at a distance of 28.58 feet, said point marking the southwest corner of a parcel currently owned by J. & K. Mould (ORV 2428, Page 550);

Thence, North 88 degrees 58 minutes 41 seconds East with the south line of said Mould parcel and passing through said iron pin found, a total distance of 311.98 feet to an iron pin set;

Thence, South 21 degrees 17 minutes 20 seconds East 475.61 feet to an iron pin set;

Thence, South 71 degrees 27 minutes 59 seconds West passing through an iron pin set for reference at a distance of 263.00 feet, a total distance of 293.00 feet to the place of beginning, containing 3.51 acres according to a survey by Chad F. Craig P.S. #8195 for Seiler & Craig Surveying, Inc. on May 22, 2023, but subject to all easements, right of ways and highways of record.

Iron pins set are 5/8" rods with caps stamped "CRAIG 8195".

Bearings are based on State Plane Grid North, NAD 83 (2011), Geoid 18A, Ohio North Zone and are intended to be used for angular determination only.

CHAD F.
CRAIG 8195

**GISTERRO STRINGTON OF THE PARTY OF

Chad F. Craig P.S.#8195 for Seiler & Craig Surveying, Inc.

NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE

EAK 6-15-23

INITIAL & DATE

PP-145





Environmental Division 555 Lexington Ave. Mansfield, OH 44907 (419)774-4520 phone (419)774-0845 fax

Review by Richland Public Health (RPH) is required for any lot split that does not have an associated

sanitary sewer tap, a sewage treatment system that will remain on lot, and/or where potential buildable lots may be created with no access to sanitary sewer system. Richland Public Health will assess existing sewage treatment system(s) to ensure proper function, establish that space remains on the lot(s) for replacement of existing sewage treatment(s), assign required area for installation of sewage treatment system(s) on new lots, and determine that any split does not encroach on required isolation distances. **Applicant Information** Name Date Wil Van Dyke 3/21/2023 Mailing Address City State Zip Bellville 6235 ST RT 546 Ohio 48813 Phone **Email** 419-886-4367 Wilvandyke@yahoo.com Site Information Site Address 6235 ST RT 546 City State **Township** Bellville Ohio 48813 Perry Total Acreage (Before Lot Splits) Parcel #(s) Acreage Per Lot(s): **Existing Home** Combining to (check if yes) **Another Lot?** х All newly created lots under five (5) acres will be required to have a soil evaluation conducted by an approved Soil Evaluator. Lot 2: All newly created lots that are 5 acres or greater, will not be required to have a soil Lot 3: evaluation conducted by an approved Soil Evaluator <u>unless</u> a building location has been determined on the new lot. Lot 4: A septic permit will not be issued for a lot until a soil evaluation has been conducted by Lot 5: an approved Soil Evaluator. As required by Ohio Administrative Code (OAC) 3701-29-08, the following information must be submitted with this application prior to review:

(1) Soil Evaluation Report for each lot in accordance with OAC 3701-2	(1)	Soil Evaluation	Report for each	ot in accordance w	vith OAC 3701-29-0	7.
---	-----	-----------------	-----------------	--------------------	--------------------	----

(2) Staked or marked locations of proposed lot corners/property lines.

(3) A survey prepared for each lot by a Registered Surveyor

Yes <a>

Yes 🔳 Yes

` ,	Scaled site drawing including: (a) acreage of each proposed lot and
	land area; (b) proposed lot lines with detail of site conditions including
	vegetation and drainage; (c) site information including easements, utilities,
	structures, wells, foundations, roads, drainage features, water bodies.
	(Include: future buildings, landscaping, pools, etc)

Yes 🔳

(5) Identification of one or more sewage treatment system type(s) that might be feasible for each lot.

Yes 🔳

Please submit this completed form, the above required documents and payment of **\$250.00 per each new** *lot* either by mail or in person to: Richland Public Health, 555 Lexington Avenue, Mansfield, OH 44907 (Checks payable to: Richland Public Health).

This evaluation does not indicate specific sewage treatment system type(s) to be installed on the lot(s). A site review for permit must be approved by RPH to determine exact specifications, type, and size of system. This evaluation is not a guarantee of system approval or type and applies to only those site conditions known at the time of inspection and documents submitted for review. The review is limited to the site conditions at time of inspection and documents submitted for review.


Applicant Signa	Applicant Signature Date		
w/i/	VAN Dyke	4-12-23	
OFFICE USE ONLY			
Final Lot Split Consideration:			
	Sanitarian Signature	Date of Approval	
Approved	Jelli Word, EHS-IT	5/31/2023	
П	Sanitarian Signature	Date of Disapproval	
☐ Disapproved			
	Sanitarian Signature	Date of Exempt Status	
Exempt			
Comments:			
Information provided with The lot split application			
did no		or existing	
<u>easlments</u>	and/or whity basements	<u> </u>	

Areas designated for installation and/or replacement of a sewage treatment system shall be undisturbed and protected from damage or disturbance. OAC 3701-29-15(P)(1)

Fee Paid	250.00
Date Paid	4-13-23
Receipt#	1990/utt
Recorded By	Lutt.
Date Recorded	4-13-23



Updated 04/12/2021



SURVEY DESCRIPTION PARCEL "A"

PART OF THE NW QUARTER OF SECTION 24 PERRY TOWNSHIP RICHLAND COUNTY, OHIO

Situated in the Township of Perry, County of Richland, State of Ohio and being a part of the Northwest quarter of Section 24 of Township 19 North, Range 19 West, and being more particularly described as follows:

Beginning for the same at a point marking the southeast corner of said quarter and being a point in the centerline of Darlington East Road (C.H. 27), and being referenced by an iron pin found on a bearing of North 01 degree 18 minutes 02 seconds West and at a distance of 15.40 feet, Thence, North 89 degrees 44 minutes 26 seconds West with the south line of said quarter and with said centerline 148.59 feet to a railroad spike found marking the intersection of said centerline with the centerline of State Route 546:

Thence, North 21 degrees 58 minutes 47 seconds West with the centerline of State Route 546, 733.59 feet to a point referenced by an iron pin found on a bearing of North 89 degrees 44 minutes 26 seconds West and at a distance of 32.41 feet;

Thence, North 21 degrees 17 minutes 20 seconds West with said centerline 675.39 feet to a point referenced by an iron pin set on a bearing of North 71 degrees 27 minutes 59 seconds East and at a distance of 30.00 feet;

Thence, North 71 degrees 27 minutes 59 seconds East passing through said iron pin set, a total distance of 293.00 feet to an iron pin set;

Thence, North 21 degrees 17 minutes 20 seconds West 475.61 feet to an iron pin set on the south line of a parcel currently owned by J. & K. Mould (ORV 2428, Page 550);

North 88 degrees 58 minutes 41 seconds East with the south line of said Mould parcel and the easterly prolongation thereof 521.19 feet to an iron pin set on the east line of said quarter;

Thence, South 01 degree 18 minutes 02 seconds East with the east line of said quarter and passing through an iron pin found at a distance of 1840.91 feet, a total distance of 1856.31 feet to the place of beginning, containing 17.43 acres according to a survey by Chad F. Craig P.S. #8195 for Seiler & Craig Surveying, Inc. on May 22, 2023, but subject to all easements, right of ways and highways of record.

Iron pins set are 5/8" rods with caps stamped "CRAIG 8195".

Bearings are based on State Plane Grid North, NAD 83 (2011), Geoid 18A, Ohio North Zone and are intended to be used for angular determination only.





Chad F. Craig P.S.#8195 for Seiler & Craig Surveying, Inc.

SURVEY DESCRIPTION PARCEL "B"

PART OF THE NW QUARTER OF SECTION 24 PERRY TOWNSHIP RICHLAND COUNTY, OHIO

Situated in the Township of Perry, County of Richland, State of Ohio and being a part of the Northwest quarter of Section 24 of Township 19 North, Range 19 West, and being more particularly described as follows:

Commencing at a point marking the southeast corner of said quarter and being a point in the centerline of Darlington East Road (C.H. 27), and being referenced by an iron pin found on a bearing of North 01 degree 18 minutes 02 seconds West and at a distance of 15.40 feet, Thence, North 89 degrees 44 minutes 26 seconds West with the south line of said quarter and with said centerline 148.59 feet to a railroad spike found marking the intersection of said centerline with the centerline of State Route 546, Thence, North 21 degrees 58 minutes 47 seconds West with the centerline of State Route 546, 733.59 feet to a point referenced by an iron pin found on a bearing of North 89 degrees 44 minutes 26 seconds West and at a distance of 32.41 feet, Thence, North 21 degrees 17 minutes 20 seconds West with said centerline 675.39 feet to a point referenced by an iron pin set on a bearing of North 71 degrees 27 minutes 59 seconds East and at a distance of 30.00 feet, said point being the place of beginning of the parcel herein described;

Thence, North 21 degrees 17 minutes 20 seconds West with said centerline 569.59 feet to a point referenced by an iron pin found on a bearing of North 88 degrees 58 minutes 41 seconds East and at a distance of 28.58 feet, said point marking the southwest corner of a parcel currently owned by J. & K. Mould (ORV 2428, Page 550);

Thence, North 88 degrees 58 minutes 41 seconds East with the south line of said Mould parcel and passing through said iron pin found, a total distance of 311.98 feet to an iron pin set;

Thence, South 21 degrees 17 minutes 20 seconds East 475.61 feet to an iron pin set;

Thence, South 71 degrees 27 minutes 59 seconds West passing through an iron pin set for reference at a distance of 263.00 feet, a total distance of 293.00 feet to the place of beginning, containing 3.51 acres according to a survey by Chad F. Craig P.S. #8195 for Seiler & Craig Surveying, Inc. on May 22, 2023, but subject to all easements, right of ways and highways of record.

Iron pins set are 5/8" rods with caps stamped "CRAIG 8195".

Bearings are based on State Plane Grid North, NAD 83 (2011), Geoid 18A, Ohio North Zone and are intended to be used for angular determination only.

CHAD

CHAD

F.

CRAIG

8195

SONAL SUPPLIFIE

MAY 3 0 2023

Chad F. Craig P.S.#8195 for Seiler & Craig Surveying, Inc.