

## SURVEYOR'S DESCRIPTION FOR **DEBORAH HART**

## **0.480** Acres

Situated in the Township of Washington, County of Richland, State of Ohio and being part of the Northwest Quarter of Section 16, Township 20, Range 18 and being more particularly described as follows:

**Commencing** at an iron pin found in the northwest corner of Lot 9 as shown in plat volume 21, page 72, said iron pin also being in the south right of way line of Hanley Road (C.H 139)(60');

Thence N 00° 00′ 00″ E, 30.00 feet to a point in the centerline of said Hanley Road (C.H 139)(60′). said point also being in the north line of said Northwest Quarter and being referenced by an iron pin found S 00° 00' 00" W, 30.00 feet from said point;

Thence N 90° 00' 00" E, 292.57 feet along said centerline of Hanley Road (C.H 139)(60') also being along said north line of said Northwest Quarter to a point being in the northeast corner of a parcel of land conveyed to John J. Mauritz Trustee by official records volume 2896, page 787, said point being referenced by an iron pin found S 00° 03' 30" W, 29.57 feet from said point and being the true place of beginning;

Thence with following FOUR courses:

- 1) N 90° 00' 00" E, 107.52 feet and continuing along said centerline of Hanley Road (C.H 139)(60') and along said north line of said Northwest Quarter to a point being the northwest corner of a parcel of land conveyed to Michael Edward Stoffer, Jr. and Trent Michael Johnson by official records volume 2898, page 830, said point being referenced by an iron pin found S 01° 47' 26" W, 29.86 feet from said point;
- S 01° 47' 26" W, 200.08 feet along said west line of said land of Michael Edward 2) Stoffer, Jr. and Trent Michael Johnson to a point being the northeast corner of a parcel of land conveyed to James D. and Janice M. Boyd by official records volume 644, page 377, said point being referenced by an iron pin found S 01° 47' 26" W, 2.82 feet from said point;
- 3) S 90° 00' 00" W, 101.47 feet along a north line of said land of James D. and Janice M. Boyd to an iron pin found in a northwest corner of said land, said iron pin also being in the east line of said land of John J. Mauritz Trustee;
- 4) N 00° 03' 30" E, 199.98 feet along said east line of said land of John J. Mauritz Trustee to the **true place of beginning**, passing through previously reverenced iron pin found at 170.41 feet and containing **0.480 acre**, more or less, and subject to all legal highways and easements of record.

Bearings are to an assumed meridian and are used to express angles only.

According to a survey made in January 2023 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

**NEW SURVEY** OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE

EAK 1-26-23 INITIAL & DATE

**PP-20** 



Roger L. Stevens

Registered Surveyor No. 7052

WASHINGTON-15G