

SURVEYOR'S DESCRIPTION FOR TIMOTHY & TAMARA SMITH

9.445 Acres

Situated in the Township of Jefferson, County of Richland, State of Ohio, being part of the Northeast Quarter of Section 35 and part of the Northwest Quarter of Section 36, Township 19, Range 18, and being more particularly described as follows:

Commencing at a centerline monument box found in the intersection of the east line of the Northeast Quarter of Section 35 also being the west line of said Northwest Quarter of Section 36 and the centerline of S.R. 95 (R/W varies);

Thence N 67° 13′ 58″ E, 312.93 feet along said centerline of S.R. 95 (R/W varies) to a point being the southeasterly corner of a parcel of land conveyed to the State of Ohio by official records volume 571, page 603, said point being referenced by an iron pin set N 40° 12′ 03″ W, 47.16 feet from said point;

Thence N 21° 42′ 47″ W, 45.41 feet along the easterly line of said land of the State of Ohio to a point being the northeasterly corner of said land, said point being referenced by an iron pin set S 65° 40′ 28″ W, 14.97 feet from said point;

Thence S 70° 46′ 11" W, 14.51 feet along the northerly line of said land of the State of Ohio to a point, said point being referenced by an iron pin set S 02° 31′ 04" E, 1.39 feet from said point, and being the **true place of beginning**;

Thence with the following FI VE courses:

- 1) S 70° 46' 11" W, 385.71 feet along said northerly line of said land of the State of Ohio to a point, said point being referenced by an iron pin set S 61° 11' 53" W, 59.06 feet from said point;
- 2) S 65° 19' 37" W, 57.14 feet and continuing along said northerly line of said land of the State of Ohio and continuing through the land of Timothy and Tamara Smith by official records 1467, page 397 to a point, said point being referenced by an iron pin set S 02° 31' 25" E, 4.64 feet from said point;
- 3) N 02° 31' 25" W, 1,044.24 feet to an iron pin set;
- 4) N 87° 37' 22" E, 422.45 feet to an iron pin set;
- 5) S 02° 31' 04" E, 910.73 feet to the true place of beginning, and containing 9.455 acres, more or less, of which 4.415 acres are in the Northeast Quarter of Section 35 and 5.040 acres are in the Northwest Quarter of Section 36 and subject to all legal highways and easements of record.;

Basis of bearings: Survey MM-232.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in July 2023 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

NEW SPLIT RICHLAND COUNTY TAX MAP OFFICE

EAK 8-25-23

INITIAL & DATE

PP-222

Roger L. Stevens

Registered Surveyor No. 7052

SM-1860P

10.079 Acres

Situated in the Township of Jefferson, County of Richland, State of Ohio, being part of the Northwest Quarter of Section 36, Township 19, Range 18, and being more particularly described as follows:

Commencing at a centerline monument box found in the intersection of the west line of said Northwest Quarter of Section 36 and the centerline of S.R. 95 (R/W varies);

Thence N 67° 13′ 58″ E, 312.93 feet along said centerline of S.R. 95 (R/W varies) to a point being the southeasterly corner of a parcel of land conveyed to the State of Ohio by official records volume 571, page 603, said point being referenced by an iron pin set N 40° 12′ 03″ W, 47.16 feet from said point and being the **true place of beginning**;

Thence with the following **SEVEN** courses:

- 1) N 21° 42' 47" W, 45.41 feet along the easterly line of said land of the State of Ohio to a point being the northeasterly corner of said land, said point being referenced by an iron pin set S 65° 40' 28" W, 14.97 feet from said point;
- 2) S 70° 46' 11" W, 14.51 feet along the northerly line of said land of the State of Ohio to a point, said point being referenced by an iron pin set S 02° 31' 04" E, 1.39 feet from said point;
- 3) N.02° 31' 04" W, 910.73 feet to an iron pin set;
- 4) N 87° 37' 22" E, 511.67 feet to an iron pin found in the northwesterly corner of a parcel of land conveyed to Chad and Christine Kemp by official records volume 2991, page 958 and passing through an iron pin found at 211.63 feet;
- 5) S 02° 31' 00" E, 757.56 feet along the west line of said land of Chad and Christine Kemp to a point being in the southwesterly corner of said land, said point also being in said centerline of S.R. 95 (R/W varies) and passing through an iron pin found at 728.59 feet
- 6) S 65° 42' 35" W, 441.51 feet along said centerline of S.R. 95 (R/W varies) to a centerline monument box found;
- 7) S 67° 13' 58" W, 77.61 feet and continuing along said centerline of S.R. 95 (R/W varies) to the **true place of beginning**, and containing 10.079 acres, more or less, and subject to all legal highways and easements of record.;

Basis of bearings: Survey MM-232.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in July 2021 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE
EAK 8-25-23

INITIAL & DATE

Roger L. Stevens

Registered Surveyor No. 7052

SM-1860P