

SURVEY DESCRIPTION

PART OF THE SE QUARTER OF SECTION 35 JACKSON TOWNSHIP RICHLAND COUNTY, OHIO

Situated in the Township of Jackson, County of Richland, State of Ohio and being a part of the Southeast quarter of Section 35 of Township 22 North, Range 19 West, and being more particularly described as follows:

Beginning for the same at an iron pin found and accepted as marking the northwest corner of the Southeast quarter of Section 35, Thence, North 89 degrees 49 minutes 29 seconds East with the north line of said quarter section 805.11 feet to an iron pin set;

Thence, South 27 degrees 01 minute 51 seconds East 233.78 feet to an iron pin found on the northeast corner of a parcel currently owned by G.E. Milliron JR. (O.R.V. 1813, P. 137);

Thence, North 89 degrees 56 minutes 49 seconds West with the north line of said Milliron parcel 937.12 feet to an iron pin found on the west line of said quarter section;

Thence, North 00 degrees 41 minutes 50 seconds East with the west line of said quarter section 249.47 feet to the place of beginning, containing 5.02 acres according to a survey by Chad F. Craig P.S. #8195 for Seiler & Craig Surveying, Inc. on August 30, 2023, but subject to all easements, right of ways and highways of record.

The grantees, his heirs and assigns do hereby covenant and agree that the parcel of land described in this instrument or any portion thereof does not constitute a principal building site under applicable zoning and will not be conveyed by said grantees, heirs and assigns independent and separate from any adjoining or contiguous parcel fronting on a public highway or street.

Iron pins set are 5/8" rods with caps stamped "CRAIG 8195".

Bearings are based on State Plane Grid North, NAD 83 (2011), Geoid 18A, Ohio North Zone and are intended to be used for angular determination only.



NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE
EAK 9-20-23

INITIAL & DATE PP-267

Chad F. Craig P.S.#8195 for Seiler & Craig Surveying, Inc.