

SURVEYOR'S DESCRIPTION FOR BRENT TAYLOR

5.022 Acres

Situated in the Township of Worthington, County of Richland, State of Ohio, being part of the Southeast Quarter of Section 13, Township 21, Range 17, and being more particularly described as follows:

Commencing at a railroad spike found in the southwest corner of said Southeast Quarter, said railroad spike also being in the intersection of the centerline of S.R. 97 (60') and the centerline of McCurdy Road (C.H. 378)(60');

Thence N 88° 12' 19" E, 1,056.85 feet along the south line of said Southeast Quarter also being along said centerline of S.R. 97 (60') to a point, said point being referenced by an iron pin set N 01° 54' 07" E, 17.71 feet from said point and being the **true place of beginning**;

Thence with the following FOUR courses:

- 1) N 01° 54' 07" E, 794.56 feet to an iron pin set and passing through previously referenced iron pin set at 17.71 feet;
- 2) S 89° 45' 14" E, 257.19 feet to an iron pin set in the west line of a parcel of land conveyed to Margaret A. Marlow by official records volume 2079, page 233;
- 3) S 01° 00' 44" E, 783.82 feet along said west line of said land of Margaret A. Marlow to a point being the southwest corner of said land, said point also being in said south line of said Southeast Quarter and being in said S.R. 97 (60'), and passing through an iron pin found at 758.85 feet;
- 4) S 88° 12' 19" W, 297.56 feet along said south line of said Southeast Quarter also being along said centerline of S.R. 97 (60') to the **true place of beginning** and containing 5.022 acres, more or less, and subject to all legal highways and easements of record.;

Basis of bearings: Survey II-157.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in February 2023 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

Roger L. Stevens

Registered Surveyor No. 7052

SM-1736A11

NEW SPLIT RICHLAND COUNTY TAX MAP OFFICE $EAK\ 3-15-23$

INITIAL & DATE

PP-63

6.964 Acres

Situated in the Township of Worthington, County of Richland, State of Ohio, being part of the Southeast Quarter of Section 13, Township 21, Range 17, and being more particularly described as follows:

Commencing at a railroad spike found in the southwest corner of said Southeast Quarter, said railroad spike also being in the intersection of the centerline of S.R. 97 (60') and the centerline of McCurdy Road (C.H. 378)(60');

Thence N 01° 04′ 11″ W, 443.04 feet along the west line of said Southeast Quarter also being along said centerline of McCurdy Road (C.H. 378)(60′) to a point, said point being referenced by an iron pin set N 88° 13′ 04″ E, 29.11 feet from said point and being the **true place of beginning**;

Thence with the following FOUR courses:

- 1) N 01° 04' 11" W, 383.95 feet and continuing along said west line of said Southeast Quarter and along said centerline of McCurdy Road (C.H. 378)(60') to a point, said point being referenced by an iron pin set N 88° 17' 30" E, 26.59 feet from said point;
- 2) N 88° 17' 30" E, 784.53 feet to an iron pin set and passing through an iron pin set at 26.59 feet;
- 3) S 03° 03' 18" E, 383.00 feet to an iron pin set;
- 4) S 88° 13' 04" W, 797.81 feet to the true place of beginning and containing 6.964 acres, more or less, and subject to all legal highways and easements of record.;

Basis of bearings: Survey II-157.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in February 2023 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

Roger L. Stevens

Registered Surveyor No. 7052

SM-1736A11

NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE $EAK\ 3-15-23$

INITIAL & DATE

PP-63