

Richland Brick, Inc.
D.V. 862 P 573

T. & C. Granly
D.V. 893 P 645

N 86° 30' 38" W 1193.97
4.950
Due S 50' E 0.70
N 86° 30' 38" W

R. H. Rhoades

O.R.V. 442 R 337

22. 215 A.C.

816 484 1120
Ready to set

Line of NE $\frac{1}{4}$ of Sec 35
Due South 131.68'
(bearing basis)
Due South 131.68'

P.O.B.

= SW cor.
of NE $\frac{1}{4}$ of
Sec 35

344.29'

N 88° 08' 34" E

• = Iron Pin set & capped

○ = Iron Pin, found

□ = Wood Post, found

Scale 1" = 200'

200

DESCRIPTION OF SURVEY FOR RICK RHOADES


PART OF NE 1/4 SECTION 35
TOWNSHIP 22 RANGE 18
WELLER TOWNSHIP
RICHLAND COUNTY, OHIO

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

FAK 5-12-03
INITIAL

Robert M. Little
Registered Surveyor # Ohio 5524

April 24, 2003



R-102

R-102

R-102

ROBERT M. LITTLE
PROFESSIONAL SURVEYOR AND ENGINEER
47 Redwood Rd - Mansfield, Ohio 44907
Phone 419 / 755-5056

DESCRIPTION OF SURVEY FOR RICK RHOADES

PART OF NE 1/4 SECTION 35
TOWNSHIP 22 RANGE 18
WELLER TOWNSHIP
RICHLAND COUNTY, OHIO

Situated in the Township of Weller, County of Richland, State of Ohio and being a part of the Northeast Quarter of Section 35, Township 22, Range 18, and being more particularly described as follows:

Beginning at an iron pin, found, marking the southwest corner of said northeast quarter of Section 35;

Thence North 88° 08' 34" East a distance of 344.29 feet to a point in the centerline of Mansfield-Savannah Road, S.R. 545, passing an iron pin, found, 40.55 Feet westerly of said centerline, at said bearing, said course being with the south line of said quarter;

Thence North 36° 49' 43" East a distance of 673.01 feet to a P.I., referenced by an iron pin, set and capped, bearing South 52° 36' 40" East a distance of 17.3 feet from said P.I., said course being with the centerline of said road;

Thence North 37° 51' 31" East a distance of 804.02 feet to a point, referenced by an iron pin, set and capped, bearing North 86° 30' 38" West a distance of 25.12 feet from said point, said course being with the centerline of said road;

Thence North 86° 30' 38" West a distance of 1,193.77 feet to a wood post, found, passing said reference iron pin, set and capped, at a distance of 25.12 feet, and passing an iron pin, found, at 391.68 feet, said course being with south lines of lands conveyed to T. and C. Gramly in Deed Volume 893, Page 645, to Richland Brick, Inc. in Deed Volume 862 Page 573, and to F. and P. Reed in Official Record Volume 443 Page 718, and with the following three lines being boundaries of said F. and P. Reed lands;

- 1) Thence Due South a distance of 128.70 feet to an iron pin, set and capped;
- 2) Thence North 86° 30' 38" West a distance of 49.50 feet to an iron pin, set and capped;
- 3) Thence Due South a distance of 1,131.62 feet to the point of


1

R-102

beginning, said course being with the west line of said quarter;


Containing 22.215 acres of land, more or less, but subject to an easement for S.R. 545 and all other easements of record.

Bearing basis: The west line of said quarter, called Due South.



Robert M. Little
Registered Surveyor # Ohio 5524

April 24, 2003



NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE
DAK 5-6-03
INITIAL DATE

R-102

2

R-102