



BRANSON FARM.

S.E. 1/4 SEC 7

15 52 A's

Survey 1-15-28.

SW 1/4
97 A's ±

3.10 A's

NE 1/4
8.05 A's ±

6.50 A's ±

4.50

S 89° 30' W 887'

N 49° 25' E
S 47° 15' W

N 46° 05' W 46° 05' W

N 43° 10' W

N 77° 49' 2" W

N 46° 47' 1" W

S 66° 08' W

8.05 A's ±

5.60 A's ±

286'

N 30° W 547'

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East

East