

North line, N.W. Qtr, Sec. 7  
 S 88° 30' E  
 1128.98'  
 Northwest Corner of the  
 Northwest Quarter, Sec. 7

Fleming Falls Rd. T.H. 270

N 88° 30' W  
 581.95'

Elmer J. Blevins &  
 Sandra L. Blevins  
 V-901, P. 180 - 1376 Ac.

N 1° 30' E  
 513.01'  
 1.645 Ac.  
 651.05'  
 S 1° 30' W

Board of County Commissioners  
 Richland County, Ohio.  
 V-603, P. 63 - 13.66 Ac.

Robert W. Neutzling &  
 Carol A. Neutzling  
 V-703, Pg. 270 - 13.21 Ac.

Robert W. Neutzling &  
 Carol A. Neutzling  
 V-703, P. 270 - 11.9 Ac.



Robert W. Neutzling &  
 Carol A. Neutzling  
 V-817, P. 391 - 7.39 Ac.

M. Viecelli  
 V-638, P. 57

Plot of Survey  
 for

Richland County Commissioners  
 Being a part of the Northwest Quarter  
 of Section 7, Township 23, Range 17,  
 Millpin Township, Richland County, Ohio.

○ Iron Pin Set  
 ⊙ Iron Pin Found  
 Basis of Bearings: Deed Vol. 603, Pg. 63



*Larry G. Blunk*  
 Larry G. Blunk  
 Registered Surveyor #8320  
 Richland County Engineers Office  
 January 10, 1989