



LEGEND

- Iron Pin Found
- ⊙ Iron Pin Set
- ⊠ Railroad Spike Set

S.E. Corner, S.E. 1/4,
Sec. 30, Twp. 23, R. 19,
Millin Twp., Richland Co., Ohio

Part of: 1.00 Acre Parcel
Location: S.E. 1/4, Sec. 30, Twp. 23, R. 19,
Millin Twp., Richland Co., Ohio
Survey For: F. L. Simmers
Survey By: Gary W. Prinz
Gary W. PRINZ
Reg. Surveyor #6398
August 13, 1978