

SURVEY DESCRIPTION

Part SW 1/4 Section 2
Monroe Township
Richland County, Ohio

Situated in the Township of Monroe, County of Richland, State of Ohio and being a part of the Southwest Quarter Section Two (Pt. SW 1/4 S-2) of Township Twenty-two (T-22), Range Seventeen (R-17), more particularly bounded and described as follows:

Commencing at a spike in the Southwest Corner of said Southwest Quarter Section 2, the same being the Point of Intersection of the centerline of State Route 603 with the centerline of State Route 39; thence South 89° 41' 20" East with said centerline of State Route 39 and the South Line of said Quarter a distance of 852.81 feet to a spike, the Place of Beginning;

THENCE, continuing South 89° 41' 20" East a distance of 313.63 feet to a spike in an existing Boundary Corner;

THENCE, North 2° 24' 40" East with an existing Boundary a distance of 566.46 feet to an iron pin;


THENCE, North 87° 35' 20" West with an existing Boundary a distance of 334.61 feet to an iron pin;

THENCE, South 0° 18' 40" West a distance of 578.35 feet to the Place of Beginning, containing 4.26 acres, be the same more or less, according to survey by Justin A. Seiler, Registered Surveyor #4421, on January 2, 1976, but subject to all legal Highways.

Gerald Eulett

Parcel "B" 4.26 acres

January 5, 1976


Justin A. Seiler
Reg. Surveyor #4421