

Trumpower Rd. T.H. 368

637.21' N 1°30'E

NW Cor. NE 1/4
Sec. 25

North Line NE 1/4

683.33'

S 87°30'E

10.0 acres ±



Frame Barn
170' from N. Line
360' from Road



Fr. House
390' from N. Line
350' from Road

N 87°30' W

683.33'

S 1°30' W

637.21'

I HEREBY CERTIFY THAT A LOCATION SURVEY OF THE ABOVE PREMISES HAS BEEN MADE, THAT THERE ARE NO ENCROACHMENTS OR EASEMENTS VISIBLE ON THE GROUND OTHER THAN THOSE SHOWN ABOVE, AND THAT IRON PIPE HAVE NOT BEEN SET UNLESS INDICATED. THIS SURVEY PROVIDED FOR TITLE COMPANY AND/OR LENDER ONLY.

Survey by *James B. Roberts*
James B. Roberts
Reg. Surveyor #4279

May 1984
Scale: 1" = 100'

↳ Iron Pin Set
↳ Iron Pin Found

Plot of Survey for
R. & A. BURKEPIKE

NE 1/4 - Sec. 25 - T22 - R17
Monroe Township
Richland County
Ohio

LOCATION SURVEY FOR: MIDLAND TITLE
MORTGAGE COMPANY: COLONIAL MTG.
GRANTOR: BURKEPIKE
GRANTEE: SCHMIDT, W. W. and Patricia
ADDRESS: Rt. 1 Trumpower Rd.,
Perryville, Ohio
RICHLAND COUNTY, OHIO
FLOOD ZONE: NO

