

588° 15' E
1328.85

335.9
53° 01' W

71'
N. 85° 56' W

639.69
S 4° 50' W

28 1/2 A
S.E. 1/4 Sec. 35
Sandusky Tp.

966.0
N 3° 25' E

7.2
N 88° 35' W

588° 50' E
1413.56

83.8 A
N.E. 1/4 Sec. 2.
Sandusky Tp

1371.57
N 0° 45' E

1392.18
S 2° 30' W

9 1/4 A. NW 1/4 Sec. 1.

2611.0
N 88° 30' W

ESTATE OF CHRISTIAN MILLER
SURVEY MADE TO DETERMINE CONTENTS.

28 1/2 Acres SE 1/4 Sec. 35 Sandusky Tp.
83.8 Acres NE 1/4 Sec. 2

Dec. 22, 1913

C.L. Bushey, Co. Surveyor.
BY
M.D.B.

111
111