

NE. corner of the West half of the NW 1/4 of Section 23

S.R. 181 and North line of Section 23

C.R. 47 and, East line of the West half of the NW 1/4 of Section 23


15.00 ACRES

N 89°-51' E  
1140.99'

S 89°-51' W  
1140.99'

N 0°-09' W  
572.66'

S 0°-09' E  
572.66'



SCALE  
1"=200'

Situated in the Northwest quarter of Section 23, Sandusky Township, T-20-N, R-20-W, Richland County, Ohio.

o - Iron Pin  
 P.K. - Survey Nail  
 R.S. - Railroad Spike  
 January 2, 1974  
 C. Randolph Strauch XXXXXX  
 Reg. Engineer # 35870  
 Reg. Surveyor #6193