

SURVEY FOR LLOYD E. HIRTZ



1"=60'

Situated in the northwest
quarter of Section number
36, Sandusky Township,
T-20, R-20, Richland
County, Ohio.

iron pin "•"
October 13, 1979
Gerald W. Riedel
Reg. Surveyor #5817
Gerald W. Riedel

