
SURVEY FOR: ANDREW & JUDITH MILLER PART OF THE SE. 1/4 OF SEC. 6, T-19, R-18, JEFFERSON TWP., RICHLAND CO., STATE OF OHIO. LOCATION: DATE: 8-15-22 JOB NUMBER: SM-1312 MATCH LINE SEE SHEET 2 07.04°C Distances shown hereon are expressed in feet and decimal parts thereof, bearings are to an assumed meridian and are 3.82 used to express angles only. CERTIFICATION: I hereby certify that the foregoing survey was prepared from actual field measurements, In accordance with Chapter 4733—37, Ohio Administrative Code and is correct to the best of my knowledge. OF R=146.91 A=140.78' △=54°54'20' C=135.46' ROGER L. B=N 20°21'28"/E **STEVENS** 7052 PEGISTERED SURVEYOR L. Stevens, P.S. #7052 Roger R=167.37A=137.10' $\Delta=46'56'00"$ C = 133.30'B=N 24*20'38" E 60 120' SCALE 1"=60' ROAD (T.H. 348)(60" 301. **LEGEND** ш 0 IRON PIN FOUND RAILROAD SPIKE FOUND 00.52 RAILROAD SPIKE SET RITTER IRON PIN SET, 5/8" DIA. ROD WITH PLASTIC CAP STAMPED "STEVENS 7052" لى OF -S. LINE SE. 1/4 SEC. 6 SHEET € BELLVILLE-JOHNSVILLE ROAD (C.H. 31)(60')



SURVEYOR'S DESCRIPTION FOR ANDREW & JUDITH MILLER

PARCEL A

Situated in the Township of Jefferson, County of Richland, State of Ohio, being part of the Southeast Quarter of Section 6, Township 19, Range 18 and being more particularly described as follows:

Commencing at a railroad spike found in the south line of said Southeast Quarter, said railroad spike also being in intersection of the centerline of Ritter Road (T.H. 348)(60') and the centerline of Bellville-Johnsville Road (C.H. 31)(60');

Thence N 00° 52' 38" E, 301.35 feet along said centerline of Ritter Road (T.H. 348)(60') to a an iron pin found in a point of curve;

Thence Northeasterly and continuing along said centerline of Ritter Road (T.H. 348)(60') on a curve to the right having a radius of 167.37 feet, an arc length of 137.10 feet, a delta angle of 46° 56' 00", a chord length of 133.30 feet and a chord bearing of N 24° 20' 38" E to a railroad spike found in a point of tangency;

Thence N 47° 48' 38" E, 66.82 feet and continuing along said centerline of Ritter Road (T.H. 348)(60') to a railroad spike found in a point of curve;

Thence Northeasterly and continuing along said centerline of Ritter Road (T.H. 348)(60') on a curve to the left having a radius of 146.91 feet, an arc length of 140.78 feet, a delta angle of 54° 54' 20", a chord length of 135.46 feet and a chord bearing of N 20° 21' 28" E to a railroad spike found in a point of tangency;

Thence N 07° 04' 09" W, 328.82 feet and continuing along said centerline of Ritter Road (T.H. 348)(60') to a point, said point being referenced by an iron pin set S 87° 58' 30" W, 14.99 feet from said point;

Thence N 01° 13' 16" W, 207.09 feet and continuing along said centerline of Ritter Road (T.H. 348)(60') to a point being the northeast corner of a 1.551 acre parcel of land conveyed to Daniel R. and Catherine E. Magers by official records volume 307, page 452, said point being referenced by an iron pin set S 88° 48' 38" W, 25.00 feet from said point and being the true place of beginning;

Thence with the following FOUR courses:

- 1) S 88° 48' 38" W, 233.43 feet along the north line of said land of Daniel R. and Catherine E. Magers to a point being the northwest corner of said land, said point also being in the east line of a parcel of land conveyed to Andrew J. and Judith W. Miller by official records volume 154, page 430 and being referenced by an iron pin found S 01° 17' 23" W, 0.83 feet from said point and passing through previously referenced iron pin set at 25.00 feet;
- N 01° 17' 23" W, 120.49 feet along said east line of said land of Andrew J. and Judith W. 2) Miller to an iron pin set;
- 3) N 88° 48' 38" E, 233.57 feet to a point being in said centerline of Ritter Road (T.H. 348)(60') and passing through an iron pin set at 208.57 feet;
- 4) S 01° 13' 16" E, 120.48 feet along said centerline of Ritter Road (T.H. 348)(60') to the true place of beginning and containing 0.646 acre, more or less, and subject to all legal highways and easements of record.

The grantees, their heirs and assigns do hereby covenant and agree that the parcel of land described in this instrument or any portion thereof does not constitute a principal building site.

Bearings are to an assumed meridian and are used to express angles only.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in August 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

NEW SPLIT RICHLAND COUNTY TAX MAP OFFICE

8-31-22 EAK

00-285

DATE

INITIAL

Roger L. Stevens Registered Surveyor No. 7052

SM-1312D

PARCEL B

Situated in the Township of Jefferson, County of Richland, State of Ohio, being part of the Southeast Quarter of Section 6, Township 19, Range 18 and being more particularly described as follows:

Commencing at a railroad spike found in the south line of said Southeast Quarter, said railroad spike also being in intersection of the centerline of Ritter Road (T.H. 348)(60') and the centerline of Bellville-Johnsville Road (C.H. 31)(60');

Thence N 00° 52' 38" E, 301.35 feet along said centerline of Ritter Road (T.H. 348)(60') to a an iron pin found in a point of curve;

Thence Northeasterly and continuing along said centerline of Ritter Road (T.H. 348)(60') on a curve to the right having a radius of 167.37 feet, an arc length of 137.10 feet, a delta angle of 46° 56' 00", a chord length of 133.30 feet and a chord bearing of N 24° 20' 38" E to a railroad spike found in a point of tangency;

Thence N 47° 48' 38" E, 66.82 feet and continuing along said centerline of Ritter Road (T.H. 348)(60') to a railroad spike found in a point of curve;

Thence Northeasterly and continuing along said centerline of Ritter Road (T.H. 348)(60') on a curve to the left having a radius of 146.91 feet, an arc length of 140.78 feet, a delta angle of 54° 54' 20", a chord length of 135.46 feet and a chord bearing of N 20° 21' 28" E to a railroad spike found in a point of tangency;

Thence N 07° 04' 09" W, 328.82 feet and continuing along said centerline of Ritter Road (T.H. 348)(60') to a point, said point being referenced by an iron pin set S 87° 58' 30" W, 14.99 feet from said point;

Thence N 01° 13' 16" W, 327.57 feet and continuing along said centerline of Ritter Road (T.H. 348)(60') to a point, said point being referenced by an iron pin set S 88° 48' 38" W, 25.00 feet from said point and being the true place of beginning;

Thence with the following **FOUR** courses:

- S 88° 48' 38" W, 233.57 feet to an iron pin set in the east line of a parcel of land conveyed 1) to Andrew J. and Judith W. Miller and passing through previously referenced iron pin set at 25.00 feet;
- N 01° 17' 23" W, 120.49 feet along said east line of said land of Andrew J. and Judith W. 2) Miller to an iron pin set in the southwest corner of a parcel of land conveyed to Stanley N. Hoptry by official records volume 2290, page 92;
- 3) N 88° 48' 38" E, 233.72 feet along the south line of said land of Stanley N. Hoptry to a point being the southeast corner of said land, said point also being in said centerline of Ritter Road (T.H. 348)(60') and being referenced by an iron pin found S 84° 13' 51" W, 11.69 feet from said point;
- 4) S 01° 13' 16" E, 120.48 feet along said centerline of Ritter Road (T.H. 348)(60') to the true place of beginning and containing 0.646 acre, more or less, and subject to all legal highways and easements of record.

The grantees, their heirs and assigns do hereby covenant and agree that the parcel of land described in this instrument or any portion thereof does not constitute a principal building site.

Bearings are to an assumed meridian and are used to express angles only.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in August 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

NEW SURVEY OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE

8-31-22 EAK DATE

INITIAL

Roger L. Stevens

Registered Surveyor No. 7052

SM-1312D