LOTS 116, 117, 118 & 119 & PART OF OUTLOT 4 IN WILD WOOD SPRINGS, & SURVEY FOR: MATHEW OVERHOLT DATE: 10-16-22 SITUATED IN THE NW. 1/4 OF SEC. 10, T-21, R-17, WORTHINGTON TWP., RICHLAND CO., STATE OF OHIO. JOB NUMBER: SM-1722 KARL WAYNE & MARILYN JEANNE SNYDER 40' O.R.V.-2208 P.-840 SCALE 1"=40' LEGEND IRON PIN FOUND IRON PIN SET, 5/8" DIA. ROD WITH PLASTIC CAP STAMPED "STEVENS 7052" 78·47'50" E .57 285. 30.03,25" BURSON P.-234 PART OF OUTLOT 4 PART OF OUTLOT 4 PART OF OUTLOT 4 (0.495 Acre) THE RESTORING HOUSE JOHN R. & RUTH E. DUNN RIVERSIDE LLC JOHN P. BURSON O.R.V.-531 P.-374 O.R.V.-2795 P. - 247253 P.-58 D..V.-829 0.8392 Acres ш **NEW SURVEY** OF EXISTING PARCEL 30.03 RICHLAND COUNTY TAX MAP OFFICE S EAK 10-28-22 INITIAL & DATE WILD WOOD SPRINGS 00-363 P. - 9P.V.-13 7 Z 30' 30, Z 30,7 Z 30' 30'Z 30 30, 7 30' 30 a 6 0 121 ලි 120 0.0413 Acre 0.0413 Acre 116 115 113 118 0.0413 Acre 0.0413 Acre GARAGE 30' 30 ₽30 30' 30' 30' 59*56'35 120.00 59°56'35" W S 90.00' -10' PATH 10' PATH 30.07[,]P L 25 30.07 30.07 30.07 30.07 30.07 L 41.79 107 106 105 104 103 108 110 109 ROGER L #7052 STEVENS 7052 Distances shown hereon are expressed in feet and decimal parts thereof. SURVEYOR Basis of bearings: Survey JJ-144. CERTIFICATION: I hereby certify that the foregoing survey was prepared from actual field measurements, In accordance with Chapter 4733-37, Ohio Administrative Code and is correct to the best of my knowledge.

LOCATION:

SURVEYOR'S DESCRIPTION FOR MATHEW OVERHOLT

LOTS 116, 117, 118, 119 & PART OF OUTLOT 4

Situated in the Township of Worthington, County of Richland, State of Ohio, being all of Lots 116, 117, 118 and 119 and being part of Outlot 4 in Wild Wood Springs as recorded in plat volume 13, page 9, being part of the Northwest Quarter of Section 10, Township 21, Range 17 and being more particularly described as follows:

Beginning at an iron pin found in the southeasterly corner of said Lot 116, said iron pin also being in the northerly line of a 10 foot path;

Thence with the following FOUR courses;

- 1) S 59° 56' 35" W, 120.00 feet along the southerly line of said Lots 116, 117, 118 and 119 also being along said northerly line of said 10 foot path to a point being the southwesterly corner of said Lot 119, said iron pin being referenced by an iron pin set S 30° 03' 25" E, 1.22 feet from said point;
- 2) N 30° 03' 25" W, 325.08 feet along the westerly line of said Lot 115 and along the easterly line of a parcel of land conveyed to John R. and Ruth E. Dunn by deed volume 829, page 58 to an iron pin set in the northeasterly corner of said land, said iron pin also being in the northerly line of said Outlot 4 and being in the southerly line of a parcel of land conveyed to Karl Wayne and Marilyn Jeanne Snyder by official records volume 2208, page 840;
- 3) N 78° 47' 50" E, 126.80 feet along said north line of said Outlot 4 also being along said southerly line of said land of Karl Wayne and Marilyn Jeanne Snyder to an iron pin found in the northwesterly corner of a parcel of land conveyed to The Restoring House Riverside LLC by official records volume 2795, page 247;
- 4) S 30° 03' 25" E, 284.10 feet along the westerly line of said land of The Restoring House Riverside LLC and along the easterly line of said Lot 116 to the place of beginning and containing 0.8392 acre, more or less, of which 0.0413 acre is in Lot 116, 0.0413 acre is in Lot 117, 0.0413 acre is in Lot 118, 0.0413 acre is in Lot 119 and 0.674 acre is in Outlot 4, and subject to all legal highways and easements of record.

Basis of bearings: Survey JJ-144.

All iron pins set are 5/8" diameter reinforcing rod with plastic cap stamped "STEVENS 7052".

According to a survey made in October 2022 by Roger L. Stevens, Ohio Registered Surveyor No. 7052.

Roger L. Stevens

Registered Surveyor No. 7052

SM-1722U2

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

EAK 10-28-22
INITIAL & DATE

VITIAL & DAI

00-363