

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL "A"

PART SE 1/4 SECTION 32 T-20 N, R-18 W WASHINGTON TOWNSHIP RICHLAND COUNTY, OHIO

August 08, 2024

Situated in the Township of Washington, County of Richland, State of Ohio and being a part of the Southeast Quarter of Section 32, Township 20-North, Range 18-West, being a portion of the lands conveyed to Carolyn Sue Brook by official record volume 3014, page 193, being more particularly described as follows:

Beginning for the same at a wooden fence post found and accepted as marking the Northeast corner of said Southeast Quarter, being referenced by an iron pin found South 39 degrees 07 minutes 34 seconds East, 13.56 feet therefrom;

Thence, the following **NINE** courses:

- 1. South 00 degrees 01 minute 21 seconds East, 994.89 feet along the east line of said quarter to an iron pin set in the centerline of Alexander Road-(T.H. 340)(60' R/W);
- 2. **North 87 degrees 00 minutes 00 seconds West, 77.26 feet** traversing the aforementioned Brook parcel, and along said centerline to an iron pin set marking a point of deflection;
- 3. **North 70 degrees 00 minutes 00 seconds West, 172.39 feet** traversing said Brook parcel, and continuing along said centerline to an iron pin set;
- 4. North 00 degrees 01 minute 21 seconds West, 251.75 feet traversing said Brook parcel, to an iron pin set;
- 5. North 35 degrees 12 minutes 22 seconds West, 132.29 feet traversing said Brook parcel to an iron pin set marking a point of curvature;
- 6. Northwesterly along a curve to the left having a radius of 240.00 feet, a delta angle of 54 degrees 50 minutes 26 seconds, and arc length of 229.72 feet, a chord bearing North 62 degrees 37 minutes 35 seconds West, and a chord distance of 221.05 feet traversing said Brook parcel to an iron pin set marking a point of tangency;

- 7. **South 89 degrees 57 minutes 11 seconds West, 174.07 feet** traversing said Brook parcel to an iron pin set on the east line of a parcel conveyed to Valley View Development Partnership, LLC by official record volume 2904, page 35;
- 8. North 00 degrees 16 minutes 27 seconds West, 470.00 feet along the east line of said Valley View Development Partnership, LLC parcel to an iron pin set in the northeast corner thereof, said iron pin also being on the north line of the aforementioned southeast quarter;
- 9. **North 89 degrees 57 minutes 11 seconds East, 687.75 feet** along the north line of said quarter to the **Place of Beginning**, and containing 10.5719 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with cap stamped "Ramsey S-8396"

According to a survey made in August 2024 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

AMMINIANA.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-6012_Parcel A.docx

NEW SPLIT
RICHLAND COUNTY

TAX MAP OFFICE

EAK 9-6-24

INITIAL & DATE

QQ-248

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL "B"

PART SE 1/4 SECTION 32 T-20 N, R-18 W WASHINGTON TOWNSHIP RICHLAND COUNTY, OHIO

August 08, 2024

Situated in the Township of Washington, County of Richland, State of Ohio and being a part of the Southeast Quarter of Section 32, Township 20-North, Range 18-West, being a portion of the lands conveyed to Carolyn Sue Brook by official record volume 3014, page 193, being more particularly described as follows:

Commencing at a wooden fence post found and accepted as marking the Northeast corner of said Southeast Quarter, being referenced by an iron pin found South 39 degrees 07 minutes 34 seconds East, 13.56 feet therefrom;

Thence, South 00 degrees 01 minute 21 seconds East, 994.89 feet along the east line of said quarter to an iron pin set in the centerline of Alexander Road-(T.H. 340)(60' R/W);

Thence, **North 87 degrees 00 minutes 00 seconds West, 77.26 feet** traversing the aforementioned Brook parcel, and along said centerline to an iron pin set marking a point of deflection;

Thence, North 70 degrees 00 minutes 00 seconds West, 172.39 feet traversing said Brook parcel, and continuing along said centerline to an iron pin set, being the Place of Beginning of the parcel herein described;

Thence, the following SEVEN courses:

- 1. North 70 degrees 00 minutes 00 seconds West, 144.53 feet traversing said Brook parcel and continuing along said centerline to an iron pin set;
- 2. South 89 degrees 33 minutes 49 seconds West, 308.95 feet traversing said Brook parcel to an iron pin set on the east line of a parcel conveyed to Valley View Development Partnership, LLC by official record volume 2904, page 35;
- 3. North 00 degrees 16 minutes 27 seconds West, 414.26 feet along the east line of said Valley View Development Partnership, LLC parcel to an iron pin set;

- 4. North 89 degrees 57 minutes 11 seconds East, 174.07 feet traversing said Brook parcel to an iron pin set marking a point of curvature;
- 5. Southeasterly along a curve to the right having a radius of 240.00 feet, a delta angle of 54 degrees 50 minutes 26 seconds, and arc length of 229.72 feet, a chord bearing South 62 degrees 37 minutes 35 seconds East, and a chord distance of 221.05 feet traversing said Brook parcel to an iron pin set marking a point of tangency;
- 6. South 35 degrees 12 minutes 22 seconds East, 132.29 feet traversing said Brook parcel to an iron pin set;
- 7. South 00 degrees 01 minute 21 seconds East, 251.75 feet traversing said Brook parcel, to the Place of Beginning, and containing 3.8915 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with cap stamped "Ramsey S-8396"

According to a survey made in August 2024 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

SM-6012_Parcel B.docx

Professional Surveyor No. 8396 For Ramsey Surveying

annillii.

NEW SPLIT RICHLAND COUNTY TAX MAP OFFICE EAK 9-6-24

INITIAL & DATE

QQ-248

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL "C"

PART SE 1/4 SECTION 32 T-20 N, R-18 W WASHINGTON TOWNSHIP RICHLAND COUNTY, OHIO

August 08, 2024

Situated in the Township of Washington, County of Richland, State of Ohio and being a part of the Southeast Quarter of Section 32, Township 20-North, Range 18-West, being a portion of the lands conveyed to Carolyn Sue Brook by official record volume 3014, page 193, being more particularly described as follows:

Commencing at a wooden fence post found and accepted as marking the Northeast corner of said Southeast Quarter, being referenced by an iron pin found South 39 degrees 07 minutes 34 seconds East, 13.56 feet therefrom;

Thence, South 00 degrees 01 minute 21 seconds East, 994.89 feet along the east line of said quarter to an iron pin set in the centerline of Alexander Road-(T.H. 340)(60' R/W), being the Place of Beginning of the parcel herein described;

Thence, the following **SIX** courses:

- 1. **South 00 degrees 01 minute 21 seconds East, 321.96 feet** along the east line of said quarter to an iron pin found in the northeast corner of a parcel conveyed to Ronald A. Distl & Mary E. Distl by official record volume 2955, page 682;
- 2. **South 89 degrees 33 minutes 49 seconds West, 681.96 feet** along the north line of said Distl parcel to an iron pin set in the southeast corner of a parcel conveyed to Valley View Development Partnership, LLC by official record volume 2904, page 35;
- 3. North 00 degrees 16 minutes 27 seconds West, 437.24 feet along the east line of said Valley View Development Partnership, LLC parcel to an iron pin set;
- 4. **North 89 degrees 33 minutes 49 seconds East, 308.95 feet** traversing said Brook parcel to an iron pin set on the aforementioned centerline of Alexander Road;
- 5. South 70 degrees 00 minutes 00 seconds East, 316.92 feet traversing said Brook parcel and along said centerline to an iron pin set marking a point of deflection;

6. **South 87 degrees 00 minutes 00 seconds East, 77.26 feet** traversing said Brook parcel and continuing along said centerline to the **Place of Beginning**, and containing 6.2766 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with cap stamped "Ramsey S-8396"

According to a survey made in August 2024 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-6012_Parcel C.docx

* NATHANIEL *

B.

RAMSEY
S-8396

**GISTERED*

NEW SURVEY OF EXISTING PARCEL RICHLAND COUNTY TAX MAP OFFICE

EAK 9-6-24

INITIAL & DATE

QQ-248



Environmental Division 555 Lexington Ave. Mansfield, OH 44907 (419)774-4520 phone

(419)774-4520 phone (419)774-0845 fax

Lot Split Application

Review by Richland Public Health (RPH) is required for any lot split that does not have an associated sanitary sewer tap, a sewage treatment system that will remain on lot, and/or where potential buildable lots may be created with no access to sanitary sewer system.

Richland Public Health will assess existing sewage treatment system(s) to ensure proper function, establish that space remains on the lot(s) for replacement of existing sewage treatment(s), assign required area for installation of sewage treatment system(s) on new lots, and determine that any split does not encroach on required isolation distances.

	required isolation distances.						
	Applicant Information						
	Name Carolyn Brook	Date 08/05/2024					
	Malling Address 598 Alexander Road	2	Cit Bell		State Ohlo	Zip 44813	
	Email		Ph	ione			
	Site Information		,				
,	Site Address	,					
	City BELLVILLE	Stat OHIO		Zip 44813	Township WASHINGTO	N	
	Parcel #(s) Total Acreage (Before Lot Splits)						
	0523600305000			20	ě		
	Acreage Per Lot(s):	Existing F		Combining to Another Lot?		+	
PARCEL B	Lot 1: 3.8915	х			All newly created lot	s under five (5) acres will	
	Lot 2:				be required to have a soil evaluation conducted by an approved Soil Evaluator.		
	Lot 3:		¥		evaluation conducte	equired to have a soil d by an approved Soil	
	Lot 4:				Evaluator <u>unloss</u> a building location has been determined on the new lot.		
	Lot 5:				A septic permit will r until a soil evaluatio an approved Soil Ev	not be issued for a lot in has been conducted by valuator.	

As required by Ohio Administrative Code (OAC) 3701-29-08, the following information must be submitted with this application prior to review:

(1) 8	Soil Evaluation	Report for	r each lot in	accordance with	OAC 3701-	29-07.
-------	-----------------	------------	---------------	-----------------	-----------	--------

(2) Staked or marked locations of proposed lot corners/property lines.

(3) A survey prepared for each lot by a Registered Surveyor

Yes I

/es

(4) Scaled site drawing including: (a) acreage of each proposed lot and land area; (b) proposed lot lines with detail of site conditions including vegetation and drainage; (c) site information including easements, utilities, structures, wells, foundations, roads, drainage features, water bodies. (Include: future buildings, landscaping, pools, etc)

Yes 🔳

(5) Identification of one or more sewage treatment system type(s) that might be feasible for each lot. Proposed replacement type: Chamber System


Yes 🔳

Please submit this completed form, the above required documents and payment of \$250.00 per each new lot either by mail or in person to: Richland Public Health, 555 Lexington Avenue, Mansfield, OH 44907 (Checks payable to: Richland Public Health).

This evaluation does not indicate specific sewage treatment system type(s) to be installed on the lot(s). A site review for permit must be approved by RPH to determine exact specifications, type, and size of system. This evaluation is not a guarantee of system approval or type and applies to only those site conditions known at the time of inspection and documents submitted for review. The review is limited to the site conditions at time of inspection and documents submitted for review.

Applicant Signa	ture	Date		
Caroles,	Brook	8-9-24		
1				
***************************************	OFFICE USE ONLY			
Final Lot Split C	onsideration:			
 /	Environmental Health Specialist/In Training Signature	Date of Approval		
Approved	Mullelle El 1 EHS	8/20/2024		
Disapproved	Environmental Health Specialist/In Training Signature	Date of Disapproval		
☐ Exempt	Environmental Health Specialist/In Training Signature	Date of Exempt Status		
- INFORMATION D	SATED FOR INSTALLTION AND/OR REPLACEMENT STURBED AND PROTECTED FROM DAMAGE OR I ROUDED WITH THE LOT SPLIT APPLICATION DID NO TILLTY EASEMENTS.	T of A SENAGE TREATMENT SYSTEM , OAC 3701-29-15(P)		
	ransforred # into fro	m original app		
Fee Paid	250,00 00, 0	yes pernets.		
Date Paid	8/5/24	SEIVEM		
Receipt #	57/7/			
Recorded By	Maa	IG 1 2 2024		
Date Recorded	Taca	W T LOCA		
		Updated 09/11/2019		

HEALTH DEPT. MAP



ZONING APPROVAL MAP

