

SEILER & CRAIG SURVEYING, INC

Douglas C. Seiler, PS & Chad F. Craig, 52 1/2 North Main Street www.seilerandcraig.com Mansfield, Fax 419-525-3696 Ohio 44902

SURVEY DESCRIPTION

WOODSIDE SUBDIVISION
MADISON TOWNSHIP, RICHLAND COUNTY, OHIO PART OF LOT #80, and PART OF LOT #81

Situated in the Township of Madison, County of Richland, State of Ohio and being a part of Lot #80 and a part of Lot #81 of the consecutively numbered lots in the Woodside Subdivision (plat reference: Volume 18, page 109), and being more particularly described as follows:

westerly prolongation thereof, a distance of 107.02 feet to an iron pin found and accepted as marking the southwest corner of said Lot #80; Beginning for the same at an iron pin set marking the southeast corner of said Lot #81; Thence, North 87 degrees 47 minutes 47 seconds West with the south line of said lot and the

Thence, North 02 degrees 30 minutes 00 seconds East with the west line of said lot, a distance of 38.74 feet to an iron pin set;

pin set on the east line of said Lot #81; Thence, North 69 degrees 05 minutes 44 seconds East a distance of 117.20 feet to an iron

Thence, South 02 degrees 51 minutes 52 seconds West with said east line, a distance of 84.74 feet to the place of beginning, containing a total of 6618 square feet, of which 2556 square feet are located within part of said Lot #80, and 4062 square feet are located within part of said Lot #81, according to survey by Douglas C. Seiler, Professional Surveyor 6869 for Seiler & Craig Surveying, Inc. on September 13, 2004.

Iron pins set are 5/8" rods with caps stamped "SEILER AND CRAIG INC."

determination only Bearings are based on an assumed meridian and are intended to be used for angular

OF EXISTING PARCEL RICHLAND COUNTY

COISTER C DOUGLAS SEILER 6869 OF 1 Douglas for Seller & C 9 Seiler PS #6869

& Craig Surveying, Inc.