SEILER & CR

SURVEYING, INC.

Douglas 419-525-3644 S.C. Seiler, PS & Chad F. Craig, PS 52 1/2 North Main Street
Mansfield, Ohio 44902 www.seilerandcraig.com Fax 419-525-3696

SURVEY DESCRIPTION

PART OF LOT #3084, PART OF LOT #3085 AND PART OF LOT #3086 CITY OF MANSFIELD, OHIO

lots in said city, and being more particularly described as follows: part of Lot #3084, a part of Lot #3085, and a part of Lot #3086 of the consecutively numbered Situated in the City of Mansfield, County of Richland,

Beginning for the same at a Mag Nail spike set marking the southeast corner of s #3086. Thence, South 89 degrees 24 minutes 16 seconds West with the south line lot, a distance of 80.57 feet to a railroad spike found; Beginning for the #3086; Thence, \$ of said Lot of said

pin found; Thence, North 00 degrees 00 minutes 13 seconds West a distance of 73.00 feet to an iron

spike found on the east line of Vennum Avenue; Thence, South 89 degrees 01 minutes 35 seconds West a distance of 89.00 feet to a railroad

Thence, North 00 degrees .74 feet to a drill hole set marking the northwest corner of said Lot #3084; 15 minutes 58 seconds East with said east line, distance

same being the south line of Marion Avenue, a distance of 96.04 feet to an iron pin found; North 67 degrees 20 minutes 59 seconds East with the north line of said lot, the

pin set; Thence, South 00 degrees 10 minutes 52 seconds West a distance of 113.80 feet to an iron

found on the west line of Lind Avenue; Thence, North 88 degrees 58 minutes 05 seconds East a distance of 80.84 feet to an iron pin

Thence, South 00 degrees 00 minutes 29 seconds East with said west line, a distance of 90.03 feet to the place of beginning, containing a total of 17196 square feet, of which 6920 square feet are located within part of said Lot #3084; 6234 square feet are located within part of said Lot #3085; and 4042 square feet are located within part of said Lot #3086, according to survey by Douglas C. Seiler, Professional Surveyor #6869 for Seiler and Craig Surveying, Inc., on November 11, 2004.

Iron pins set are 5/8" rods with caps stamped "SEILER AND CRAIG, INC."

determination only. Bearings are based on an assumed meridian and are intended to be used for angular

OF EXISTING PARCEL NITIAL CO RICHLAND COUNTY TAX MAP OFFICE NEW SURVEY

DATE PATE PVET

for Seiler Douglas eiler & C \circ èiler PS #6869

Craig Surveying, Inc.