


- LEGEND**
- ▲ MAG NAIL FOUND
 - IRON NAIL/PIPE FOUND
 - CONCRETE ANCHOR FOUND
 - IRON PIN SET WITH 1/8" CAP
 - REBAR SET WITH 1/8" CAP
 - SOUNDED S.I. NAIL

Distances shown hereon are expressed in feet and decimal parts thereof.

Basis of Bearings: Survey F-2-259

CERTIFICATION: I hereby state that the foregoing survey was prepared from actual field measurements in accordance with Chapter 4733-37, Ohio Administrative Code.

By: *Roger L. Stevens*
 Roger L. Stevens, P.S. #7052
 & Associates, Inc.
 Surveyors
 Date: 7-13-12



SCHAEFER, JOHNSON, LICHTENWALDER & ASSOCIATES, INC.
 Consulting Engineers & Surveyors
 10000 W. 12th St., Suite 100
 Overland Park, KS 66213
 Phone: (913) 666-1200
 Fax: (913) 666-1201
 Email: info@schaeferjohnson.com

SURVEY MADE AT THE REQUEST OF:
 TODD & COLETTE DUNN
 PART OF THE SOUTHWEST QUARTER OF SECTION 19
 & SEBASTIAN TOWNSHIP, RICHLAND COUNTY, OHIO
 FOR THE PURPOSES OF THE ALLEY & LOTS
 15 & 22, SHELBY GALLON ROAD
 RICHLAND COUNTY, OHIO

DATE: 7-13-12
 TIME: 1:40 PM

DATE	BY	SCALE	SHEET
07/27/2012	R.L.S.	1" = 50'	1 OF 1
08/20/2012	R.L.S.	1" = 50'	1 OF 1

