


SURVEY FOR

GEORGE ROUSH

PT. S.W. 1/4 SEC. 20
PLYMOUTH TWP.
RICHLAND CO.
OHIO



4.21 A.

IRON PIPE MARK ALL CORNERS
INDICATED BY "

FIELD BOOK # 5
PAGE 59

REG. SURVEYOR # 3485
DATE Oct 15, 1942

HAZELBRUSH RD.

T. H. 59 SEC. 20
SEC. 29

SHELBY

N-438

PT \equiv $1/2 - SE 1/4 - Sec 19$

Beg at pt on E line of $1/2 - 1/4$ line 65.01 S. of N.E. cor

th S. $88^{\circ}45'W - 80.19$ to W line of $1/2 - 1/4$

th $S 1^{\circ}20'E 46.06$

th $N 89^{\circ}E - 80.10$ to pt on E $1/4$ line

th $N 30^{\circ}W$ on $E 1/4$ line 46.02 the place of beg

cont 23 At also pt of the SW $1/4$ of Sec 20

Be at pt on W $1/4$ line 51.07 N of SW cor

th $S 89^{\circ}30'E 79.20$ to pt on $E 1/2 - 1/4$ line

th $N 104^{\circ}21'W 33.06$

th $N 79.05$ to pt on W $1/4$ line

th $S 39'E 33.05$ to beg

Cont 16 At

Smooth
Sec

Sec. 20