

## RAMSEY SURVEYING

**Professional Land Surveying Services** 

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

August 23, 2021

## LEGAL DESCRIPTION

**Situated** in the State of Ohio, County of Richland, Township of Sharon; being a part of the Northwest Quarter of Section 20, Township 22-North, Range 19-West, and being land conveyed to David L. Stigall by official record volume 2525, page 465, being more particularly described as follows:

**Commencing** at a survey spike found and accepted as being the intersection of the centerline of State Route 61-(60' R/W) and the West line of said Quarter;

Thence North 89 degrees 54 minutes 19 seconds East, 411.85 feet along said centerline of State Route 61 to a point being in a southeast corner of a parcel conveyed to Joann Rand by official record volume 1669, page 286, said point also being the Place of Beginning of the parcel described herein;

Thence, the following **TEN** Courses:

- 1. North 00 degrees 36 minutes 49 seconds East, 184.30 feet along an east line of said Rand parcel to an iron pipe found in a northeast corner thereof, passing through an iron pin found for reference at 26.29 feet;
- 2. North 88 degrees 56 minutes 27 seconds West, 14.91 feet along a north line of said Rand parcel to an iron pipe found in an interior corner thereof;
- 3. North 00 degrees 40 minutes 55 seconds East, 117.45 feet along an east line of said Rand parcel to an iron pipe found in an interior corner thereof;
- 4. **South 89 degrees 55 minutes 27 seconds East, 25.73 feet** along a south line of said Rand parcel to an iron pin set in a southeast corner thereof;
- 5. North 00 degrees 38 minutes 54 seconds East, 350.00 feet along an east line of said Rand parcel to an iron pin found on the south line of a parcel conveyed to Thomas L. and Janet L. Clabaaugh by official record volume 1975, page 435;
- 6. **North 88 degrees 41 minutes 35 seconds East, 297.01 feet** along the said south line of Clabaugh parcel to an iron pin set in a northwest corner of a parcel conveyed to Gail E. and Violet A. Kaufman by official record volume 2229, page 666;

- 7. **South 00 degrees 06 minutes 33 seconds West, 322.41 feet** along a west line of said Kaufman parcel to an iron pin found in an interior corner thereof;
- 8. **South 41 degrees 33 minutes 12 seconds West, 181.36 feet** along a northwesterly line of said Kaufman parcel to an iron pipe found in a northwest corner thereof;
- 9. South 00 degrees 28 minutes 26 seconds West, 200.29 feet along a west line of said Kaufman parcel and the west line of a parcel conveyed to Department of Transportation by official record volume 1022, page 549, to a point on the aforementioned centerline of State Route 61, passing through an iron pin found for reference at 171.29 feet;
- 10. **South 89 degrees 54 minutes 19 seconds West, 192.52 feet** along said centerline of State Route 61 to the **Place of Beginning**, containing 3.8849 acres, more or less, and subject to all legal highways, easements, leases, and use restrictions of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with plastic cap stamped "Ramsey S-8396"

According to a survey made in August 2021 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-5604 legal

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

 $\frac{EAK}{INITIAL}$   $\frac{9-23-21}{INITIAL}$ 

*NN-373*