

| CURVE | RADIUS | <u> ARC_LENGTH</u> | <u> CHORD LENGTH</u> | <u> CHORD BEARING</u> | DELTA ANGLE |
|-------|---------|--------------------|----------------------|-----------------------|-------------|
| C1 | 1432.69 | 108.63 | 108.60' | S 80°16'29" W | 4*20'39" |
| C2 | 1432.69 | 267.70 ' | 267.31' | N 72°44'59" E | 10°42'21" |



O IRON PIN FOUND

⊗ R/W MONUMENT FOUND

● IRON PIN SET-5/8" REBAR SET WITH I.D. CAP STAMPED "RAMSEY S-8396"

Distances shown hereon are expressed in feet and decimal parts thereof. $\,$


Bearings are to an assumed meridian and are used to express angles only.

CERTIFICATION: I hereby state that the foregoing survey was prepared from actual field measurements, In accordance with Chapter 4733—37, Ohio Administrative Code.

By: 05/24/2023

Nathaniel B. Ramsey, P.S. #8396
For Ramsey Surveying

Date



RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

SURVEY MADE AT THE REQUEST OF SHANE MYERS

PART OF THE NORTHWEST QUARTER
OF SECTION 11, JACKSON TOWNSHIP
T-22 N, R-19 W
RICHIAND COUNTY, OHIO

OHEOKED
1" SCALE
80' O

| DRAWN | CHECKED | 1 = 80' | 0.5 /24 / 2023 | | JOB NO: SM - 5.558 | SHEET 1 OF 1

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

June 8, 2023

Situated in the Township of Jackson, County of Richland, State of Ohio, and being a part of the Northwest Quarter, Section 11, Township 22-North, Range 19-West and being a portion of a parcel conveyed to Jodi L. Myers by official record volume 2652, page 587 of the Richland County Recorder's records and being more particularly described as follows:

Commencing at an iron pin found and accepted as marking the Southeast corner of said Quarter;

Thence, North 00 degrees 51 minutes 17 seconds West, 2044.81 feet along the east line of said Quarter to a point in the centerline of Ashland-Shelby Road-State Route 96-(60' R/W), passing through an iron pin found for reference at 2013.91 feet;

Thence, South 82 degrees 26 minutes 48 seconds West, 555.32 feet, along said centerline, to a point of curvature, being referenced by a right of way monument found South 41 degrees 28 minutes 15 seconds West, 45.88 feet therefrom;

Thence, southwesterly along a curve to the left having a radius of 1432.69 feet, an arc length of 108.63 feet, a delta angle of 4 degrees 20 minutes 39 seconds, a chord bearing South 80 degrees 16 minutes 29 seconds West, and a chord distance of 108.60 feet, continuing along said centerline, to a point, being the Place of Beginning of the parcel herein described;

Thence, the following **FIVE** courses:

- 1. **South 00 degrees 51 minutes 17 seconds East, 472.22 feet** to an iron pin set, and passing through an iron pin set for reference at 30.58 feet;
- 2. South 89 degrees 08 minutes 43 seconds West, 303.28 feet to an iron pin set;
- 3. North 00 degrees 51 minutes 17 seconds West, 378.08 feet to a point on the aforementioned centerline of Ashland-Shelby Road-State Route 96-(60' R/W), and passing through an iron pin set for reference at 345.78 feet;
- 4. North 67 degrees 23 minutes 48 seconds East, 50.42 feet along said centerline to a point of curvature, being referenced by an iron pin set South 22 degrees 36 minutes 12 seconds East, 30.00 feet therefrom;

5. Northeasterly along a curve to the right having a radius of 1432.69 feet, an arc length of 267.70 feet, a delta angle of 10 degrees 42 minutes 21 seconds, a chord bearing North 72 degrees 44 minutes 59 seconds East, and a chord distance of 267.31 feet, continuing along said centerline, to the Place of Beginning, containing 3.0000 acres, more or less, and subject to all legal highways, easements, leases, and use restrictions of record.

Bearings are to an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with plastic cap stamped "Ramsey S-8396"

According to a survey made June 2023 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-5558.docx

* NATHANIEL *

B. RAMSEY

S-8396

***CS-8396

***CS-8396

***CS-8396

***CS-8396

***CS-8396

***CS-8396

***CS-8396

***CS-8396

NEW SPLIT
RICHLAND COUNTY
TAX MAP OFFICE

EAK 6-30-23

INITIAL & DATE

PP-172





Environmental Division 555 Lexington Ave. Mansfield, OH 44907 (419)774-4520 phone (419)774-0845 fax

Lot Split Application

| Review by Richland Public Health (RPH) is required sanitary sewer tap, a sewage treatment system that may be created with no access to sanitary sewer sys | vill remain on lot, and/or where p | | | | | |
|---|------------------------------------|--|--|--|--|--|
| Richland Public Health will assess existing sewage to that space remains on the lot(s) for replacement of e installation of sewage treatment system(s) on new lo required isolation distances. | sisting sewage treatment(s), ass | ign required area for | | | | |
| Applicant Information | Manager in Angle Fig. 19 of 1919 | | | | | |
| Name Jodi Myers | Da | te 6-9-2023 | | | | |
| Mailing Address 1996 E Smiley Rd. | City Shelby Sta | ate Old Zip 44875 | | | | |
| Email jodinyers 3@ gmail. Com Phone 419 961 3569 | | | | | | |
| Site Information | | | | | | |
| Site Address St. Rite 96 E | , | South and Applied Court | | | | |
| City Shelby State OH Zip 44875 Township Tack Son | | | | | | |
| Parcel #(s) | | | | | | |
| 0163226011000 | 77.61 | p = 2/2 | | | | |
| Acreage Per Lot(s): Existing Home Combining to (check if yes) Another Lot? | | | | | | |
| Lot 1: 3.00 | | reated lots under five (5) acres will | | | | |
| Lot 2: | be required conducted | d to have a soil evaluation by an approved Soil Evaluator. | | | | |
| Lot 3: | greater, wi | All newly created lots that are 5 acres or greater, will not be required to have a soil evaluation conducted by an approved Soil Evaluator <u>unless</u> a building location has been determined on the new lot. | | | | |
| Lot 4: | Evaluator <u>u</u> | | | | | |
| Lot 5: | until a soil | ermit will not be issued for a lot evaluation has been conducted by ed Soil Evaluator. | | | | |
| As required by Ohio Administrative Code (OAC) submitted with this application prior to review: | 701-29-08, the following infor | mation must be | | | | |
| (1) Soil Evaluation Report for each lot in accordance (2) Staked or marked locations of proposed local (3) A survey prepared for each lot by a Registration | t corners/property lines. | Yes V Yes V | | | | |

(4) Scaled site drawing including: (a) acreage of each proposed lot and land area; (b) proposed lot lines with detail of site conditions including vegetation and drainage; (c) site information including easements, utilities, structures, wells, foundations, roads, drainage features, water bodies. (Include: future buildings, landscaping, pools, etc)

Yes 🔽

(5) Identification of one or more sewage treatment system type(s) that might be feasible for each lot.

Yes 🔽

Please submit this completed form, the above required documents and payment of \$250.00 per each new lot either by mail or in person to: Richland Public Health, 555 Lexington Avenue, Mansfield, OH 44907 (Checks payable to: Richland Public Health).

This evaluation does not indicate specific sewage treatment system type(s) to be installed on the lot(s). A site review for permit must be approved by RPH to determine exact specifications, type, and size of system. This evaluation is not a guarantee of system approval or type and applies to only those site conditions known at the time of inspection and documents submitted for review. The review is limited to the site conditions at time of inspection and documents submitted for review.

| Applicant Signa | ture | Date | | | | | |
|---|--|-----------------------------|--|--|--|--|--|
| Joh | Si Myers | 6-9-2023 | | | | | |
| OFFICE USE ONLY | | | | | | | |
| Final Lot Split C | consideration: | | | | | | |
| Approved | Environmental Health Specialist/In Training Sign | ature Date of Approval | | | | | |
| ☐ Disapproved | Environmental Health Specialist/In Training Sign | ature Date of Disapproval | | | | | |
| ☐ Exempt | Environmental Health Specialist/In Training Sign | ature Date of Exempt Status | | | | | |
| Comments: Information provided with the lot split Application did not indicate any potential or existing ease ments and or utility easements | | | | | | | |
| Fee Paid Date Paid Receipt # Recorded By Date Recorded | 250,00 6/12/23 15/19/ | | | | | | |

Areas designated for installation and or replacement of a sewage treatment system shall be undistribed and protected from damage or disturbance. OAC 3701-29-15(P)(1)

