



PLAT OF PROPERTY SURVEY
 FOR
LARRY FRALEY
 PART OF INLOT NUMBER 162 & VACATED ALLEY
 SHELBY, RICHLAND COUNTY, OHIO

EAST SMILEY AVE - 60'



SCALE - 1" = 40'

○ IRON PIPE PLACED
 ● IRON PIPE FOUND
 ⊕ RR SPIKE PLACED
 † MARK MADE

PREPARED BY:

F. E. Krocka
 F. E. KROCKA & ASSOCIATES

F. E. KROCKA
 OHIO REG SURVEYOR NO. 3702
 DATE: OCTOBER 29, 1973