


PLAT OF PROPERTY SURVEY
 JOHN DAVIS
 PART OF LOT NO. 49
 CITY OF SHELBY, RICHLAND COUNTY, OHIO



SCALE: 1" = 40'

- IRON PIPE FOUND
- IRON PIPE PLACED
- MONUMENT FOUND

PREPARED BY:
 F. E. KROCKA & ASSOCIATES
 FRED E. KROCKA
 OHIO REGISTERED SURVEYOR NO. 3702
 DATE: AUGUST 25, 1976
 REVISED (NORTH PARCEL) AUGUST 3, 1977