


PLAT OF PROPERTY SURVEY
 DR. WILLIAM MAKO, JR.
 PART OF OUTLOT NUMBER NINE (9)
 CITY OF SHELBY, RICHLAND COUNTY, OHIO



- IRON PIPE FOUND
- RAILROAD SPIKE PLACED
- IRON PIPE PLACED

PREPARED BY

F. E. KROCKA & ASSOCIATES

FRED E. KROCKA

OHIO REGISTERED SURVEYOR NO. 3702
 DATE: MARCH, 1978

SCALE - 1" = 50'

