A 9 PROPERTY SURVEY

W S AGNES Ģ S F m J

TOWNSHIP H JACKSON NORTHEAST TWENTY-TWO TOWNSHIP, QUARTER, (22) RICHLAND RANGE SECTION COUNTY, OHIO NINETEEN (19) TWENTY-THREE (23)

RD.

N.E. 1/4, SEC. 23 LINE 5 NORTH 200 0'81 NORTH 208) VILL (T. H. 328.80 \$.89°53'47 |218.00' | MESOUTH OF PARCEL 200.00 HINOS D 1.00 LINE, SCALE: I"= ACRES PARCEL Z N.89°53'47 S. 89°53'47" QUARTER, W SEC × 104.71 5.07 S 1102.09 ACRES

200.02' N. 0° 45' W.

PREPARED **.** Y8 200

KROCKA & ASSOCIATES

FRED E REGISTERED H 16, 1973 KROCKA SURVEYOR NO. 3702

F. E. KROCKA & ASSOCIATES ENGINEERING AND SURVEYING 23 WEST MAIN STREET SHELBY, OHIO 44878 PHONE: (419) 342-4556

38 Glenwood Drive SHELBY, OHIO one: (419) 342-6631

DESCRIPTION: Parcel A*- Being part of the Northeast Quarter of Section twe three (23), Township twenty-two (22), Range nineteen (19), Jackson Township, DESCRIPTION: Quarter of Section twenty-

right-of-ways now on record. thence due south on a line parallel to the centerline of Springmill North Rodistance of 200.00 feet to an iron pipe; thence N 89°53'47" W on a line parate to the north property line a distance of 218.00 feet to an iron pipe in the containing 1.0 acres more or less, but subject to all legal easements and public line of Springmill North Road and which pipe is the real point of beginning and tance of 200,00 feet to an iron pipe; thence \$ 89053.47" E on a line parallel to the south line of said quartersection a distance of 218,00 feet to an iron pipe; along the centerline of the Springmill North Road a distance of 328.80 feet to an iron pipe which is the real point of beginning of the parcel herein described; thence continuing due north along the centerline of Springmill North Road a distance of 200.00 feet to an iron pipe; thence S 89053.47" E on a line parallel to Richland County, Ohio and being more particularly described as follows:

Beginning for the same at the southwest corner of the Northeast Cuarter of Section twenty-three (23), thence east along the south line of the Northeast Quarter of said section a distance of 640.50 feet to an iron pipe in the centerline of the Springmill North Road (Township Highway No. an iron pipe in the No. 208); thence due W on a line parallel North Road

DESCRIPTION: Parcel B-- Being part of the Northeast Quarter of Section twenty-three (23), Township twenty-two (22), Range ninteen (19), Jackson Township, Rich-DESCRIPTION:

feet to an iron pipe thence due south on a line parallel to the centerline of Springmill North Road a distance of 200.00 feet to an iron pipe and which iron pipe is the real point of beginning and containing 5.07 acres more or less, but of the Springmill North Road (Township Highway No. 208); thence due north along the centerline of the Springmill North Road a distance of 328.80 feet to an iron pipe; thence S 89°53"47" E on a line parallel to the south line of said quarterning of the parcel herein described; thence continuing S 89°53"47" E on a line parallel to the south line of said quartersection a distance of 1,104.71 feet to an iron pipe; thence N 0°45' W a distance of 200.02 feet to an iron pipe; thence N a line parallel to the south property line a distance of 1,102.09 subject to all legal easements and public right-of-ways now on record. of Section twenty-three (23), thence east along the south line of the Northeast Quarter of said section a distance of 640.50 feet to an iron pipe in the centerline land County, Ohio and being more particularly described as follows:

Beginning for the same at the southwest corner of the Northeast Quarter

Certification: and iron pipe placed I hereby certify that surveys have been made of the above pro ឧន indicated.

F. E. KROCKA AND ASSOCIATES

Fred E. Krocka

Ohio Registered Surveyor No. 3702 Date: March 16, 1973