

SURVEY DESCRIPTION

Part SW 1/4 Section 26
Sandusky Township
Richland County, Ohio

Situated in the Township of Sandusky, County of Richland, State of Ohio and being a part of the Southwest Quarter Section Twenty-six (SW 1/4 S-26) in Township Twenty (T-20), Range Twenty (R-20), more particularly bounded and described as follows:

Commencing at an iron pin marking the Point of Intersection of the South Line of the Southwest Quarter of said Section 26 with the centerline of Crestline Bloominggrove Road (Township Highway 47) and running thence North $1^{\circ} 05'$ West along and with said centerline a distance of 221.5 feet to the Point of Beginning;

THENCE, continuing North $1^{\circ} 05'$ West along and with said centerline a distance of 224 feet;


THENCE, South $89^{\circ} 32' 20''$ West with an existing Boundary a distance of 247.5 feet to an existing fence post;

THENCE, South $1^{\circ} 05'$ East a distance of 224 feet to an iron pin set in an existing Boundary Line;

THENCE, North $89^{\circ} 32' 20''$ East a distance of 247.5 feet to the Point of Beginning, containing 1.27 acres, be the same more or less, according to survey by Justin A. Seiler, Registered Surveyor #4421, on September 10, 1976, but subject to all legal Highways.

William Biddle

September 15, 1976


Justin A. Seiler
Reg. Surveyor #4421