

DESCRIPTION: Being part of the Southwest Quarter of Section Eleven (11), Township Twenty-one (21), Range Twenty (20), Sharon Township; Richland County, Ohio and being more particularly described as follows: Beginning for the same at the Northwest Corner of the Southwest Quarter of Section Eleven (11), thence East along the north line of said Quarter Section a distance of 1,326.0 feet to a point in the centerline of the Hines North Road (T.H.-178); thence due South along the centerline of T.H.-178 a distance of 1,483.2 feet to an iron pipe which is the real point of beginning of the parcel herein described; thence S 89°49' Wa distance of 427.50 feet to an iron pipe; thence due South and parallel to T.H.-178 a distance of 305.80 feet to an iron pipe; thence N 89°49' E on a line parallel to the north line a distance of 427.50 feet to an iron pipe in the centerline of T.H. 178; thence due North along the centerline of T.H.-178 a distance of 305.80 feet to an iron pipe which is the real point of beginning of the parcel herein described and containing 3.0 acres more or less but subject to all legal easements and right-of-ways.

Certification: I hereby certify that a survey of the above property has been made and iron pipe placed as indicated.

Fred E. Krocka

Ohio Registered Surveyor No. 3702

F. E. KROCKA AND ASSOCIATES

Date: March 17, 1969