

August 20, 1966

Ohio Registered Surveyor #3702

KROCKA, HAUGER AND ASSOCIATES

Ohio Registered Surveyor No. 3702 on August 20, 1966.

DESCRIPTION: Being part of the Southwest Quarter of Section Eleven (11), Township Twenty-one (21), Range Twenty (20), Sharon Township, Richland County, Ohio and being more particularly described as follows: Beginning for the same at the Northwest Corner of the Southwest Quarter of Section Eleven (11), thence East along the north line of said Quarter Section a distance of 1,326.0 feet to a point in the centerline of the Hines North Road (T.H.-178); thence South along the centerline of T.H.-178 a distance of 1,333.20 feet to an iron pipe which is the real point of beginning of the parcel herein described; thence S 89°49' W a distance of 580.80 feet to an iron pipe; thence South and parallel to T.H.-178 a distance of 150.0 feet to an iron pipe; thence N 89°49' E on a line parallel to the north line a distance of 580.80 feet to an iron pipe in the centerline of T.H.-178; thence North along the centerline of T.H.-178 a distance of 150.0 feet to an iron pipe which is the real point of beginning of the parcel herein described and containing 2.0 acres more or less but subject to all legal easements and right-of-ways and all in accordance to a survey made by Fred E. Krocka, Ohio Registered Surveyor No. 3702 on August 20, 1966.

SCALE 1"=100'

