


PLAT OF PROPERTY SURVEY
GERALD A. & JOYCE HAWK
 PART OF THE SOUTHEAST QUARTER OF SECTION NINETEEN (19)
 TOWNSHIP TWENTY-TWO (22) RANGE NINETEEN (19)
 SHARON TOWNSHIP, RICHLAND COUNTY, OHIO



SCALE - 1" = 100'

DESCRIPTION: Being part of the Southeast Quarter of Section Nineteen (19), Township Twenty-two (22), Range Nineteen (19); Sharon Township, Richland County, Ohio and being more particularly described as follows: Beginning for the same at an iron pipe in the centerline of the Shelby-Galion Road (State Route No. 61) and which iron pipe is the northeast corner of the Southeast Quarter of Section Nineteen (19); thence S 89°28' W along the Shelby-Galion Road (north line of southeast Quarter of Section Nineteen (19) a distance of 80.0 feet to an iron pipe which is the real point of beginning of the parcel herein described; thence continuing S 89°28' W along the centerline of the Shelby-Galion Road a distance of 848.96 feet to an iron pipe; thence due South on a line parallel to the west line of said Quarter Section a distance of 74.25 feet to an iron pipe; thence N 89°28' E on a line parallel to the north line of said Quarter Section a distance of 74.25 feet to an iron pipe; thence due South on a line parallel to the west line of said Quarter Section a distance of 225.47 feet to an iron pipe; thence N 89°12' E a distance of 773.72 feet to an iron pipe; thence N 0°12' E on a line parallel to the east line of said Quarter Section a distance of 296.13 feet to an iron pipe in the centerline of the Shelby-Galion Road which iron pipe is the real point of beginning and containing 5.42 acres more or less but subject to all legal easements and public right-of-ways now on record.

Certification: I hereby certify that I have made a survey of the above property and have placed iron pipe as indicated.

Date: April 4, 1970

Fred E. Krocka
 Fred E. Krocka, Ohio Registered Surveyor No. 3702