



Situated in the Northwest quarter of Section 36, Tp. 21, Rg. 20, Sharon Twp., Richland County, Ohio.

NOTE: This survey plat shows the difference between the property line of deed record (dotted line) and property line of occupation (solid line).

- - Railroad spike found
 - - #6 re-bar set
 - - Survey nail set
- Gerald W. Riedel
Ohio surveyor 5817
June 8, 1983