


A 3.8 FT. DEFECIENCY
EXIST BETWEEN THIRD
ST. AND FOURTH ST.
THIS WAS PROPORTIONED
TO EACH LOT WHICH
GIVES THE DIMENSIONS
SHOWN.

SURVEY FOR
IRVING CLOSE

LOT # 1159
SHELBY
OHIO



IRON PIPE MARK "O" ALL CORNERS
INDICATED BY "O"

Charles P. Brown
REG. SURVEYOR # 3485
DATE *July 8, 1948*