



PLAT OF PROPERTY SURVEY
DR. WILLIAM MAKO, JR.
 PART OF OUTLOT NUMBER NINE (9)
 CITY OF SHELBY, RICHLAND COUNTY, OHIO



#1

- ⊙ IRON PIPE FOUND
- RAILROAD SPIKE PLACED
- IRON PIPE PLACED

PREPARED BY
F.E. KROCKA & ASSOCIATES
Fred E. Krocka
FRED E. KROCKA
 OHIO REGISTERED SURVEYOR NO. 3702
 DATE: MARCH , 1978

SCALE - 1" = 50'