

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL A

Situated in the Township of Franklin, County of Richland, State of Ohio and being a part of the Northwest Quarter of Section 27, Township 22-North, Range 18-West, being portion of a a parcel conveyed to Judy K. Montgomery by official record volume 2562, page 862 and being more particularly described as follows:

Beginning for the same at a point in the southeast corner of said Northwest Quarter, being referenced by an iron pin found North 08 degrees 37 minutes 54 seconds West, 5.26 feet therefrom;

Thence, the following FOUR Courses:

- 1. South 89 degrees 45 minutes 58 seconds West, 299.43 feet along the south line of said Quarter to an iron pin found in the southeast corner of a parcel conveyed to Mark Davis by official record volume 2540, page 356;
- 2. North 00 degrees 26 minutes 50 seconds West, 380.74 feet along the east line of said Davis parcel to an iron pin set, passing by an iron pin found for reference North 00 degrees 00 minutes 27 seconds West, 30.41 feet from the southeast corner of said Davis parcel;
- 3. North 89 degrees 45 minutes 58 seconds East, 300.88 feet traversing aforementioned Montgomery parcel to a 2" Magnail spike set on the east line of said Quarter, said spike also being on the centerline of Frank Road-(T.H. 450)(30' R/W), passing through an iron pin set for reference at 270.88 feet;
- 4. South 00 degrees 13 minutes 44 seconds East, 380.74 feet along the east line of said Quarter and said centerline of Frank Road to the **Place of Beginning** and containing 2.6235 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" diameter rebar with plastic cap stamped "Ramsey S-8396".

According to a survey made in March 2022 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-5673 A

NEW SPLIT RICHLAND COUNTY TAX MAP OFFICE

INITIAL DATE 00-301

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL B

Situated in the Township of Franklin, County of Richland, State of Ohio and being a part of the Northwest Quarter of Section 27, Township 22-North, Range 18-West, being a portion of a parcel conveyed to Judy K. Montgomery by official record volume 2562, page 862 and being more particularly described as follows:

Commencing at a point in the southeast corner of said Northwest Quarter, being referenced by an iron pin found North 08 degrees 37 minutes 54 seconds West, 5.26 feet from said point;

Thence, North 00 degrees 13 minutes 44 seconds West, 380.74 feet along the east line of said quarter and the centerline of Frank Road-(T.H. 450)(30' R/W) to a 2" Magnail spike set, being the **Place of Beginning** of the parcel herein described;

Thence, the following FOUR Courses:

- 1. **South 89 degrees 45 minutes 58 seconds West, 300.88 feet** to an iron pin set on the east line of a parcel conveyed to Mark Davis by official record volume 2540, page 356, passing through an iron pin set for reference at 30.00 feet;
- 2. **North 00 degrees 26 minutes 50 seconds West, 347.74 feet** along the east line of said Davis parcel to a point in the northeast corner thereof, said point also being on the south line of a parcel conveyed to Daniel L. Montgomery and Regina D. Montgomery by official record volume 2337, page 81, being referenced by a "T" post found North 00 degrees 26 minutes 50 seconds West, 0.26 feet therefrom;
- 3. North 89 degrees 22 minutes 12 seconds East, 302.21 feet along said south line of Montgomery parcel to a railroad spike found in the southeast corner thereof, said spike also being on the east line of said Quarter and on the aforementioned centerline of Frank Road;
- 4. **South 00 degrees 13 minutes 44 seconds East, 349.83 feet** along the East line of Said Quarter and said centerline of Frank Road to the **Place of Beginning** and containing 2.4145 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" diameter rebar with plastic cap stamped "Ramsey S-8396".

According to a survey made in March 2022 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

EAK 9-15-22
INITIAL DATE

00-301

Nathaniel B. Ramsey Professional Surveyor No. 8396

For Ramsey Surveying SM-5673_B

* NATHANIEL *

B.

RAMSEY
S-8396

FEGISTERED.



Environmental Division 555 Lexington Ave. Mansfield, OH 44907 (419)774-4520 phone (419)774-0845 fax

Lot Split Application

Review by Richland Public Health (RPH) is required for any lot split that does not have an associated sanitary sewer tap, a sewage treatment system that will remain on lot, and/or where potential buildable lots may be created with no access to sanitary sewer system.

Richland Public Health will assess existing sewage treatment system(s) to ensure proper function, establish that space remains on the lot(s) for replacement of existing sewage treatment(s), assign required area for installation of sewage treatment system(s) on new lots, and determine that any split does not encroach on required isolation distances. Applicant Information Name Date Judy Montgomery 8-11-2022 Mailing Address City State Zip 3089 Frank rd Mansfield 44903Frank rd **Email** Site Information Site Address Frank rd City State Zip Township mansfield 44903 OH Franklin Parcel #(s) Total Acreage (Before Lot Splits) 0114012410000 5 Acreage Per Lot(s): **Existing Home** Combining to (check if yes) Lot 1: 2.6235 **Another Lot?** \Box All newly created lots under five (5) acres will Lot 2: 2.4145 be required to have a soil evaluation conducted by an approved Soil Evaluator. All newly created lots that are 5 acres or greater, will not be required to have a soil Lot 3:_____ evaluation conducted by an approved Soil Evaluator <u>unless</u> a building location has been determined on the new lot. Lot 4: A septic permit will not be issued for a lot until a soil evaluation has been conducted by Lot 5: an approved Soil Evaluator. As required by Ohio Administrative Code (OAC) 3701-29-08, the following information must be submitted with this application prior to review:

111	Sail Evaluation Dancet	for each let in accordance with OAO 2704 00	07
,	Son Evaluation Report	for each lot in accordance with OAC 3701-29	-1)/

(2) Staked or marked locations of proposed lot corners/property lines.

(3) A survey prepared for each lot by a Registered Surveyor

Yes <

Yes Yes

AUG 1 2 2022

Date

(4) Scaled site drawing including: (a) acreage of each proposed lot and land area; (b) proposed lot lines with detail of site conditions including vegetation and drainage; (c) site information including easements, utilities, structures, wells, foundations, roads, drainage features, water bodies. (Include: future buildings, landscaping, pools, etc)

(5) Identification of one or more sewage treatment system type(s) that might be feasible for each lot.

Applicant Signature

Yes 🔳

Yes 🔳

Please submit this completed form, the above required documents and payment of **\$250.00** per each new **lot** either by mail or in person to: Richland Public Health, 555 Lexington Avenue, Mansfield, OH 44907 (Checks payable to: Richland Public Health).

This evaluation does not indicate specific sewage treatment system type(s) to be installed on the lot(s). A site review for permit must be approved by RPH to determine exact specifications, type, and size of system. This evaluation is not a guarantee of system approval or type and applies to only those site conditions known at the time of inspection and documents submitted for review. The review is limited to the site conditions at time of inspection and documents submitted for review.

Approved	Sanitarian Signature	Date of Approval 8-18-2022
Disapproved	Sanitarian Signature	Date of Disapproval
Exempt	Sanitarian Signature	Date of Exempt Status
	2500CC X	· Original application
	100 C	1.1
Date Paid	4-20-22	IST) submitted on 4/26
Date Paid Receipt #	4-20-22 (BK3651	Original application (ST) submitted on 4/26
Fee Paid Date Paid Receipt # Recorded By Date Recorded	4-310-32 (BK31051)	erson that filled out

