

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL "A"

PART SE 1/4 SECTION 11 T-21 N, R-20 W SHARON TOWNSHIP RICHLAND COUNTY, OHIO

September 16, 2024

Situated in the Township of Sharon, County of Richland, State of Ohio and being a part of the Southeast Quarter of Section 11, Township 21-North, Range 20-West, being a portion of the lands conveyed to Bryan E. Bloom by official record volume 2895, page 763, being more particularly described as follows:

Commencing at the intersection of the west line of said Quarter with the centerline of Shelby-Bucyrus Road-(State Route 96)(60' R/W), being referenced by an iron pin found North 00 degrees 07 minutes 13 seconds West, 31.16 feet therefrom;

Thence, North 74 degrees 11 minutes 47 seconds East, 405.97 feet along said centerline of Shelby-Bucyrus Road-(State Route 96) to a point in the southeast corner of a parcel conveyed to Twila A. Schroeder by official record volume 915, page 873, being the Place of Beginning of the parcel herein described;

Thence, the following FOUR courses:

- 1. North 05 degrees 52 minutes 53 seconds West, 520.00 feet along the east line of said Schroeder parcel to a point, and passing through an iron pin set for reference at 30.46 feet;
- 2. South 86 degrees 48 minutes 32 seconds East, 352.00 feet traversing the aforementioned Bloom parcel to an iron pin set and passing through an iron pin set for reference at 20.00 feet;
- 3. **South 00 degrees 49 minutes 16 seconds West, 415.00 feet** traversing said Bloom parcel to point on the aforementioned centerline of Shelby-Bucyrus Road-(State Route 96), and passing through an iron pin set for reference at 383.69 feet;
- 4. **South 74 degrees 11 minutes 47 seconds West, 303.70 feet** along said centerline to the **Place of Beginning**, and containing 3.4609 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with cap stamped "Ramsey S-8396"

According to a survey made in September 2024 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-6040_Parcel A.docx



NEW SPLIT RICHLAND COUNTY TAX MAP OFFICE

EAK 10-21-24

INITIAL & DATE

QQ-299

RAMSEY SURVEYING

Professional Land Surveying Services

283 Eby Road Shiloh, Ohio 44878 TEL (419) 512-2596 FAX (419) 522-0399 EMAIL nramsey@ramsey-surveying.com

LEGAL DESCRIPTION

PARCEL "B"

PART SE 1/4 SECTION 11 T-21 N, R-20 W SHARON TOWNSHIP RICHLAND COUNTY, OHIO

September 16, 2024

Situated in the Township of Sharon, County of Richland, State of Ohio and being a part of the Southeast Quarter of Section 11, Township 21-North, Range 20-West, being a portion of the lands conveyed to Bryan E. Bloom by official record volume 2895, page 763, being more particularly described as follows:

Commencing at the intersection of the west line of said Quarter with the centerline of Shelby-Bucyrus Road-(State Route 96)(60' R/W), being referenced by an iron pin found North 00 degrees 07 minutes 13 seconds West, 31.16 feet therefrom;

Thence, North 74 degrees 11 minutes 47 seconds East, 709.67 feet along said centerline of Shelby-Bucyrus Road-(State Route 96) to the Place of Beginning of the parcel herein described;

Thence, the following SIX courses:

- 1. North 00 degrees 49 minutes 16 seconds East, 415.00 feet traversing said the aforementioned Bloom parcel to an iron pin set, passing through and iron pin set for reference at 31.31 feet;
- 2. **North 86 degrees 48 minutes 32 seconds West, 352.00 feet** traversing said Bloom parcel to a point on the west line thereof, being on the east line of a parcel conveyed to Twila Schroeder by official record volume 915, page 873 and passing through an iron pin set for reference at 332.00 feet;
- 3. North 05 degrees 52 minutes 53 seconds West, 136.22 feet along the east line of said Schroeder parcel to an iron pipe found in the northeast corner thereof, said iron pipe also being on the south line of a parcel conveyed to Shelley A. Schroeder by official record volume 2085, page 623;

- 4. **South 84 degrees 12 minutes 57 seconds East, 614.24 feet** along the south line of said Shelley A. Schroeder parcel and the south line of a parcel conveyed to Erica A. Schroeder, Nathan M. Schroeder, and Lauren O. Schroeder by official record volume 1344, page 302 to an iron pin set in an existing interior corner of said Erica A. Schroeder, Etal. parcel;
- 5. **South 00 degrees 49 minutes 16 seconds West, 438.75 feet** along a west line of said Erica A. Schroeder, Etal. parcel to a point in a southwest corner thereof, said point also being on the aforementioned centerline of Shelby-Bucyrus Road-(State Route 96), and passing through an iron pipe found for reference at 407.44 feet;
- 6. **South 74 degrees 11 minutes 47 seconds West, 255.00 feet** along said centerline to the **Place of Beginning**, and containing 3.7663 acres, more or less, and subject to all legal highways, leases, servitudes, use restrictions, and easements of record.

Bearings are based on an assumed meridian and are used to express angles only.

Iron pins set are 5/8" rebar with cap stamped "Ramsey S-8396"

The grantees, their heirs, successors, and/or assigns do hereby covenant and agree that the parcel of land described by this instrument will not be use as a building site that requires a sewage treatment system for any reason without the approval of Richland Public Health. Approval of this lot split does not guarantee a sewage treatment system can be sited on this property should the lot be evaluated for future residential or commercial use.

According to a survey made in September 2024 by Nathaniel B. Ramsey, Ohio Registered Professional Surveyor No. 8396.

Nathaniel B. Ramsey

Professional Surveyor No. 8396

For Ramsey Surveying SM-6040_Parcel B.docx

* NATHANIEL *

B. RAMSEY
S-8396

**FGISTERED

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

EAK 10-21-24

INITIAL & DATE

QQ-299





Environmental Division 555 Lexington Ave. Mansfield, OH 44907

(419)774-4520 phone (419)774-0845 fax

Lot Split Application

Review by Richland Public Health (RPH) is required for any lot split that does not have an associated sanitary sewer tap, a sewage treatment system that will remain on lot, and/or where potential buildable lots may be created with no access to sanitary sewer system.

Richland Public Health will assess existing sewage treatment system(s) to ensure proper function, establish that space remains on the lot(s) for replacement of existing sewage treatment(s), assign required area for installation of sewage treatment system(s) on new lots, and determine that any split does not encroach on required isolation distances.

Applicant Information

Name Bryan Bloom		Date 09/24/2024	
Mailing Address 5486 State Route 96	City Shelby	State OH	Zip 44875
Email bryanbloom74@yahoo.com	Phone 567-241-1153		

Site Information

Site Address ₅₄₈₆ STATE ROUTE 96 W, SHELBY 44875				
CitySHELBY	State OH - Ohio	Zip 44875	Township Sharon Township	
Parcel #(s) ₀₄₄₄₇₀₀₅₀₃₀₀₀		Total Acreage (Be 7.23	efore Lot Splits)	

Acreage Per Lot(s):	Existing Home (check if yes)	Combining to Another Lot?	
'A" Lot 1:3.4609	$X \square$		All newly created lots under five (5) acres will
Lot 2:3.7663			be required to have a soil evaluation conducted by an approved Soil Evaluator.
Lot 3:			All newly created lots that are 5 acres or greater, will not be required to have a soil evaluation conducted by an approved Soil Evaluator unless a building location has been
Lot 4:			determined on the new lot.
Lot 5:			A septic permit will not be issued for a lot until a soil evaluation has been conducted by an approved Soil Evaluator.

As required by Ohio Administrative Code (OAC) 3701-29-08, the following information must be submitted with this application prior to review:

- (1) Soil Evaluation Report for each lot in accordance with OAC 3701-29-07.
- (2) Staked or marked locations of proposed lot corners/property lines.
- (3) A survey prepared for each lot by a Registered Surveyor

Voc [

Yes 🏻

'es X

(4) Scaled site drawing including: (a) acreage of each proposed lot and land area; (b) proposed lot lines with detail of site conditions including vegetation and drainage; (c) site information including easements, utilities, structures, wells, foundations, roads, drainage features, water bodies. (Include: future buildings, landscaping, pools, etc)

(5) Identification of one or more sewage treatment system type(s) that might be Yes X feasible for each lot. Chambers or Mound per paperwork

Please submit this completed form, the above required documents and payment of \$250.00 per each new lot either by mail or in person to: Richland Public Health, 555 Lexington Avenue, Mansfield, OH 44907 (Checks payable to: Richland Public Health).

This evaluation does not indicate specific sewage treatment system type(s) to be installed on the lot(s). A site review for permit must be approved by RPH to determine exact specifications, type, and size of system. This evaluation is not a guarantee of system approval or type and applies to only those site conditions known at the time of inspection and documents submitted for review. The review is limited to the site conditions at time of inspection and documents submitted for review.

Applicant Signa	ature Byyan	E blank	Date 09/24/2024
	OF	FICE USE ONLY	
Final Lot Split C	onsideration:		
Approved	Environmental Health Spo	ecialist/In Training Signature	Date of Approval
Disapproved	Environmental Health Spo	ecialist/In Training Signature	Date of Disapproval
☐ Exempt	Environmental Health Spo	ecialist/In Training Signature	Date of Exempt Status
Comments: PArcel "I Ef when nelshe	B" Will be a property of	**	reichland public Her
Fee Paid Date Paid Receipt # Recorded By Date Recorded	250.00 9/24/24 17/208 3.0 9/24/24	this lot sq not lindi or exis	tion provided with built application did cate any potential ting easements ity easements
Areas des	ignated for	installatio	Updated 09/11/2019
be und	1sturbed An	age treatm	n And or ent system (STS) from damage
CHSTUI DAY	THE , DAC ST	01-19(1)(1)(1))

